



# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jun-28-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Emmanuel Ramos <b>Worker Name:</b> Luis N Ortiz <b>Worker Name:</b> _____ 0 <b>Worker Name:</b> N/A	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 15 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jun-28-14 <b>Received Date:</b> Jun-28-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> _____ ASB-0913-0335-AW <b>Worker ID:</b> _____ ASB-0414-0117-AW <b>Worker ID:</b> _____ 0 <b>Worker ID:</b> _____ N/A
--	--

**Project Description:** Cleaning Rooms # 19 , # 2 and 20.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-280614-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-280614-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-280614-ASB-JS-03	Emmanuel Ramos, Cleaning Room # 19	E	7:26	8:03	1.6	59.2	100	6	7.6	0.0497	0.0456	0.0497	< 0.0294
1161-280614-ASB-JS-04	Emmanuel Ramos, Cleaning Room # 19	PRCE	8:04	11:50	1.6	361.6	100	12	15.3	0.0163	0.0075	0.0163	
1161-280614-ASB-JS-05	Emmanuel Ramos, Cleaning Room # 19	PRCE	13:24	15:10	1.4	148.4	100	24.5	31.2	0.0810	0.0182	0.0810	
1161-280614-ASB-JS-06	Luis N Ortiz, Cleaning Room # 2	PRCE	7:32	11:54	1.6	419.2	100	20.5	26.1	0.0240	0.0064	0.0240	< 0.0260
1161-280614-ASB-JS-07	Luis N Ortiz, Cleaning Room # 2	PRCE	13:27	15:15	1.5	162.0	100	19	24.2	0.0575	0.0167	0.0575	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b> _____	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b> Date: <u>July 25 2014</u>
<b>Date:</b> Jun-28-14		<b>Date:</b> _____	





**ALTOL ENVIRONMENTAL SERVICES, INC.**  
 PO BOX 359 MERCEDITA, PR 00715-0359  
**FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS**

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jun-28-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Emmanuel Ramos <b>Worker Name:</b> Luis N Ortiz <b>Worker Name:</b> _____ 0 <b>Worker Name:</b> N/A	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 15 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jun-28-14 <b>Received Date:</b> Jun-28-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0913-0335-AW <b>Worker ID:</b> ASB-0414-0117-AW <b>Worker ID:</b> 0 <b>Worker ID:</b> N/A
--	--

**Project Description:** Cleaning Rooms # 19 , # 2 and 20.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-280614- ASB-JS-08	Inside Room # 19	CE	7:28	11:51	1.6	420.8	100	16.5	21.0	0.0192	0.0064	0.0192	
1161-280614- ASB-JS-09	Inside Room # 19	CE	13:25	15:11	2.5	265.0	100	17	21.7	0.0315	0.0102	0.0315	
1161-280614- ASB-JS-10	Inside Room # 2	CE	7:34	11:55	2.3	600.3	100	26	33.1	0.0212	0.0045	0.0212	
1161-280614- ASB-JS-11	Inside Room # 2	CE	13:30	15:16	2.5	265.0	100	21	26.8	0.0389	0.0102	0.0389	
1161-280614- ASB-JS-12	Outside Room # 19 ( Decon)	OS	7:29	11:52	2.4	631.2	100	8.5	10.8	0.0066	0.0043	0.0066	
1161-280614- ASB-JS-13	Outside Room # 19 ( Decon)	OS	13:26	15:12	2.5	265.0	100	5	6.4	0.0093	0.0102	< 0.0102	
1161-280614- ASB-JS-14	Outside Room # 2 ( Decon)	OS	7:36	11:57	2.3	600.3	100	6.5	8.3	0.0053	0.0045	0.0053	

*MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal  
 T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.*

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b> _____  <b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b>  <i>July -25-2014</i>
<b>Date:</b> Jun-28-14	<b>Date:</b> _____	





# ALTOL ENVIRONMENTAL SERVICES, INC.


PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions						<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo							
<b>Contact:</b> Melvin Feliciano						<b>Total Samples:</b> 15 <b>Job Number:</b> ENJ-1161							
<b>Phone / Fax/Email:</b> 787-426-1597						<b>Custody Record #:</b>							
<b>Sampling Date:</b> Jun-28-14 <b>Analytical Method:</b> NIOSH 7400						<b>Collected ID:</b> ASB-0912-0558-MS							
<b>Collected By:</b> Jose A Santos						<b>Delivery Date:</b> Jun-28-14							
<b>Delivery By:</b> Jose A Santos						<b>Received Date:</b> Jun-28-14							
<b>Received By:</b> Jose A Santos						<b>AIHA Lab ID:</b> 199763							
<b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b>						<b>Worker ID:</b> ASB-0913-0335-AW							
<b>Worker Name:</b> Emmanuel Ramos						<b>Worker ID:</b> ASB-0414-0117-AW							
<b>Worker Name:</b> Luis N Ortiz						<b>Worker ID:</b> 0							
<b>Worker Name:</b> 0						<b>Worker ID:</b> N/A							
<b>Worker Name:</b> N/A													
<b>Project Description:</b> Cleaning Rooms # 19 , # 2 and 20.													

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-280614-ASB-JS-15	Outside Area ( Decon ) Room # 2	OS	13:31	15:17	2.5	265.0	100	9.5	12.1	0.0176	0.0102	0.0176	

*MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.*

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b>	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b> 
<b>Date:</b>		<b>Date:</b>	July 25-2014





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

Customer Name: <b>Homeca Recycling and Demolitions</b>	Project Name: <b>1 ra Unidad Esc Jorge Lucas Valdiviezo</b>
Contact: <b>Melvin Feliciano</b>	Total Samples: <b>15</b> Job Number: <b>ENJ-1161</b>
Phone / Fax/Email: <b>787-426-1597</b>	Worker Name: <b>Emmanuel Ramos</b> Worker ID: <b>ASB-0913-0335-AW</b>
Collected By: <b>Jose A Santos</b> <b>ASB-0912-0558-MS</b>	Worker Name: <b>Luis N Ortiz</b> Worker ID: <b>ASB-0414-0117-AW</b>
Analyzed By Lab: <b>Altol Chemical Environmental Laboratory, Inc.</b>	Worker Name: Worker ID:
AIHA Lab ID: <b>199763</b>	Worker Name: <b>N/A</b> Worker ID: <b>N/A</b>

Project Description: Cleaning Rooms # 19 , # 2 and 20.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS28061401	Jun-28-14	1161-280614-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---
JS28061402	Jun-28-14	1161-280614-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---
JS28061403	Jun-28-14	1161-280614-ASB-JS-03	Emmanuel Ramos, Cleaning Room # 19	LV-2019	7:26	8:03	1.6	1.6	1.6	59.2	X			37
JS28061404	Jun-28-14	1161-280614-ASB-JS-04	Emmanuel Ramos, Cleaning Room # 19	LV-2019	8:04	11:50	1.6	1.6	1.6	361.6	X			226
JS28061405	Jun-28-14	1161-280614-ASB-JS-05	Emmanuel Ramos, Cleaning Room # 19	LV-2019	13:24	15:10	1.6	1.4	1.4	148.4	X			106
JS28061406	Jun-28-14	1161-280614-ASB-JS-06	Luis N Ortiz, Cleaning Room # 2	LV-2027	7:32	11:54	1.6	1.6	1.6	419.2	X			262
JS28061407	Jun-28-14	1161-280614-ASB-JS-07	Luis N Ortiz, Cleaning Room # 2	LV-2027	13:27	15:15	1.6	1.5	1.5	162.0	X			108
JS28061408	Jun-28-14	1161-280614-ASB-JS-08	Inside Room # 19	LV-5087	7:28	11:51	1.6	1.6	1.6	420.8	X			263
JS28061409	Jun-28-14	1161-280614-ASB-JS-09	Inside Room # 19	LV-5087	13:25	15:11	2.5	2.5	2.5	265.0	X			106

Turn Around Time: Normal: 7 days <u>  X  </u>		Rush: 24 hours <u>          </u>		Rush: 16 hours <u>          </u>	
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:
Jose A Santos					
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jun-28-14					Jun-28-14

July-25-2014





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

Customer Name: <b>Homeca Recycling and Demolitions</b>	Project Name: <b>1 ra Unidad Esc Jorge Lucas Valdiviezo</b>
Contact: <b>Melvin Feliciano</b>	Total Samples: <b>15</b> Job Number: <b>ENJ-1161</b>
Phone / Fax/Email: <b>787-426-1597</b>	Worker Name: <b>Emmanuel Ramos</b> Worker ID: <b>ASB-0913-0335-AW</b>
Collected By: <b>Jose A Santos</b> <b>ASB-0912-0558-MS</b>	Worker Name: <b>Luis N Ortiz</b> Worker ID: <b>ASB-0414-0117-AW</b>
Analyzed By Lab: <b>Altol Chemical Environmental Laboratory, Inc.</b>	Worker Name: Worker ID:
AIHA Lab ID: <b>199763</b>	Worker Name: <b>N/A</b> Worker ID: <b>N/A</b>

Project Description: Cleaning Rooms # 19 , # 2 and 20.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS28061410	Jun-28-14	1161-280614-ASB-JS-10	Inside Room # 2	LV-1047	7:34	11:55	2.5	2.3	2.3	600.3	X			261
JS28061411	Jun-28-14	1161-280614-ASB-JS-11	Inside Room # 2	LV-1047	13:30	15:16	2.5	2.5	2.5	265.0	X			106
JS28061412	Jun-28-14	1161-280614-ASB-JS-12	Outside Room # 19 ( Decon)	LV-5093	7:29	11:52	2.5	2.4	2.4	631.2	X			263
JS28061413	Jun-28-14	1161-280614-ASB-JS-13	Outside Room # 19 ( Decon)	LV-5093	13:26	15:12	2.5	2.5	2.5	265.0	X			106
JS28061414	Jun-28-14	1161-280614-ASB-JS-14	Outside Room # 2 ( Decon)	LV-5052	7:36	11:57	2.5	2.3	2.3	600.3	X			261
JS28061415	Jun-28-14	1161-280614-ASB-JS-15	Outside Room # 2 ( Decon)	LV-5052	13:31	15:17	2.5	2.5	2.5	265.0	X			106

Turn Around Time: Normal: 7 days <u>  X  </u>		Rush: 24 hours <u>          </u>		Rush: 16 hours <u>          </u>	
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:
Jose A Santos					Jose A Santos
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jun-28-14					Jun-28-14

*July-25-2014*





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jun-30-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Eliceo Caraballo <b>Worker Name:</b> Alexis J Rivera <b>Worker Name:</b> _____ 0 <b>Worker Name:</b> N/A	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 15 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-30-14 <b>Received Date:</b> Jul-30-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> _____ ASB-1213-0505-AW <b>Worker ID:</b> _____ ASB-0414-0119-AW <b>Worker ID:</b> _____ 0 <b>Worker ID:</b> _____ N/A
---	--

**Project Description:** Cleaning Rooms # 19 , # 2 and 20.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-300614-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-300614-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-300614-ASB-JS-03	Eliceo Caraballo, Cleaning Room # 19	E	7:28	8:00	1.6	51.2	100	5	6.4	0.0479	0.0527	< 0.0527	< 0.0234
1161-300614-ASB-JS-04	Eliceo Caraballo, Cleaning Room # 19	PRCE	8:01	11:43	1.6	355.2	100	10	12.7	0.0138	0.0076	0.0138	
1161-300614-ASB-JS-05	Eliceo Caraballo, Cleaning Room # 19	PRCE	13:15	14:32	1.4	107.8	100	18.5	23.6	0.0842	0.0250	0.0842	
1161-300614-ASB-JS-06	Alexis Joel, Cleaning Room # 2 & 20	PRCE	7:32	11:48	1.6	409.6	100	16	20.4	0.0192	0.0066	0.0192	< 0.0201
1161-300614-ASB-JS-07	Alexis Joel, Cleaning Room # 2 & 20	PRCE	13:20	16:45	1.5	307.5	100	14.5	18.5	0.0231	0.0088	0.0231	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician <a href="mailto:jose.santos@altolenterprises.com">jose.santos@altolenterprises.com</a> Phone: 787-507-1627	<b>Signature:</b> _____	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager <a href="mailto:carlos.ocasio@altolenterprises.com">carlos.ocasio@altolenterprises.com</a> Phone: 787-835-4242 / 4229	<b>Signature:</b> _____
<b>Date:</b> Jun-30-14		<b>Date:</b> _____	





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jun-30-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Eliceo Caraballo <b>Worker Name:</b> Alexis J Rivera <b>Worker Name:</b> _____ 0 <b>Worker Name:</b> N/A						<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 15 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-30-14 <b>Received Date:</b> Jul-30-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> _____ ASB-1213-0505-AW <b>Worker ID:</b> _____ ASB-0414-0119-AW <b>Worker ID:</b> _____ 0 <b>Worker ID:</b> _____ N/A							
<b>Project Description:</b> Cleaning Rooms # 19 , # 2 and 20.													
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-300614-ASB-JS-08	Inside Room # 19	CE	7:29	11:44	2.5	637.5	100	13	16.6	0.0100	0.0042	0.0100	
1161-300614-ASB-JS-09	Inside Room # 19	CE	13:16	14:33	2.5	192.5	100	14	17.8	0.0357	0.0140	0.0357	
1161-300614-ASB-JS-10	Inside Room # 2 & 20	CE	7:33	11:49	2.3	588.8	100	21	26.8	0.0175	0.0046	0.0175	
1161-300614-ASB-JS-11	Inside Room # 2 & 20	CE	13:21	16:47	2.5	515.0	100	15	19.1	0.0143	0.0052	0.0143	
1161-300614-ASB-JS-12	Outside Room # 19 ( Decon)	OS	7:31	11:45	2.4	609.6	100	5	6.4	0.0040	0.0044	< 0.0044	
1161-300614-ASB-JS-13	Outside Room # 19 ( Decon)	OS	13:17	14:34	2.5	192.5	100	7	8.9	0.0178	0.0140	0.0178	
1161-300614-ASB-JS-14	Outside Room # 2 & 20 ( Decon)	OS	7:34	11:50	2.3	588.8	100	10	12.7	0.0083	0.0046	0.0083	
<i>MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.</i>													
<b>Reported By:</b> Jose A Santos Environmental Technician <a href="mailto:jose.santos@altolenterprises.com">jose.santos@altolenterprises.com</a> Phone: 787-507-1627			<b>Signature:</b> _____			<b>Verified By:</b> Carlos Ocasio Altol Operation Manager <a href="mailto:carlos.ocasio@altolenterprises.com">carlos.ocasio@altolenterprises.com</a> Phone: 787-835-4242 / 4229			<b>Signature:</b> _____				
<b>Date:</b> Jun-30-14			<b>Date:</b> _____										





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jun-30-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos      Altol Chemical Environmental Laboratory, Inc. <b>Worker Name:</b> Eliceo Caraballo <b>Worker Name:</b> Alexis J Rivera <b>Worker Name:</b> _____ 0 <b>Worker Name:</b> N/A	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 15 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-30-14 <b>Received Date:</b> Jul-30-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> _____ ASB-1213-0505-AW <b>Worker ID:</b> _____ ASB-0414-0119-AW <b>Worker ID:</b> _____ 0 <b>Worker ID:</b> _____ N/A
---	--

**Project Description:** Cleaning Rooms # 19 , # 2 and 20.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-300614-ASB-JS-15	Outside Room # 2 & 20 ( Decon)	OS	13:22	16:48	2.5	515.0	100	11.5	14.6	0.0110	0.0052	0.0110	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b> _____	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b> _____
<b>Date:</b> _____		<b>Date:</b> _____	





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

Customer Name: <b>Homeca Recycling and Demolitions</b>	Project Name: <b>1 ra Unidad Esc Jorge Lucas Valdiviezo</b>
Contact: <b>Melvin Feliciano</b>	Total Samples: <b>15</b> Job Number: <b>ENJ-1161</b>
Phone / Fax/Email: <b>787-426-1597</b>	Worker Name: <b>Eliceo Caraballo</b> Worker ID: <b>ASB-1213-0505-AW</b>
Collected By: <b>Jose A Santos</b> <b>ASB-0912-0558-MS</b>	Worker Name: <b>Alexis J Rivera</b> Worker ID: <b>ASB-0414-0119-AW</b>
Analyzed By Lab: <b>Altol Chemical Environmental Laboratory, Inc.</b>	Worker Name: Worker ID:
AIHA Lab ID: <b>199763</b>	Worker Name: <b>N/A</b> Worker ID: <b>N/A</b>

Project Description: Cleaning Rooms # 19 , # 2 and 20.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS30061401	Jun-30-14	1161-300614-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---
JS30061402	Jun-30-14	1161-300614-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---
JS30061403	Jun-30-14	1161-300614-ASB-JS-03	Eliceo Caraballo, Cleaning Room # 19	LV-2019	7:28	8:00	1.6	1.6	1.6	51.2	X			32
JS30061404	Jun-30-14	1161-300614-ASB-JS-04	Eliceo Caraballo, Cleaning Room # 19	LV-2019	8:01	11:43	1.6	1.6	1.6	355.2	X			222
JS30061405	Jun-30-14	1161-300614-ASB-JS-05	Eliceo Caraballo, Cleaning Room # 19	LV-2019	13:15	14:32	1.6	1.4	1.4	107.8	X			77
JS30061406	Jun-30-14	1161-300614-ASB-JS-06	Alexis Joel, Cleaning Room # 2 & 20	LV-2027	7:32	11:48	1.6	1.6	1.6	409.6	X			256
JS30061407	Jun-30-14	1161-300614-ASB-JS-07	Alexis Joel, Cleaning Room # 2 & 20	LV-2027	13:20	16:45	1.6	1.5	1.5	307.5	X			205
JS30061408	Jun-30-14	1161-300614-ASB-JS-08	Inside Room # 19	LV-5087	7:29	11:44	2.5	2.5	2.5	637.5	X			255
JS30061409	Jun-30-14	1161-300614-ASB-JS-09	Inside Room # 19	LV-5087	13:16	14:33	2.5	2.5	2.5	192.5	X			77

Turn Around Time: Normal: 7 days <u>  X  </u>				Rush: 24 hours _____				Rush: 16 hours _____			
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:					
Jose A Santos						Jose A Santos					
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:					
Jun-30-14						Jun-30-14					

*July 25 2014*





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

Customer Name: <u>Homeca Recycling and Demolitions</u>	Project Name: <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u>	
Contact: <u>Melvin Feliciano</u>	Total Samples: <u>15</u>	Job Number: <u>ENJ-1161</u>
Phone / Fax/Email: <u>787-426-1597</u>	Worker Name: <u>Eliceo Caraballo</u>	Worker ID: <u>ASB-1213-0505-AW</u>
Collected By: <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u>	Worker Name: <u>Alexis J Rivera</u>	Worker ID: <u>ASB-0414-0119-AW</u>
Analized By Lab: <u>Altol Chemical Environmental Laboratory, Inc.</u>	Worker Name: _____	Worker ID: _____
AIHA Lab ID: <u>199763</u>	Worker Name: <u>N/A</u>	Worker ID: <u>N/A</u>

Project Description: Cleaning Rooms # 19 , # 2 and 20.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos			Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM	Air		
JS30061410	Jun-30-14	1161-300614-ASB-JS-10	Inside Room # 2 & 20	LV-1047	7:33	11:49	2.5	2.3	2.3	588.8	X				256
JS30061411	Jun-30-14	1161-300614-ASB-JS-11	Inside Room # 2 & 20	LV-1047	13:21	16:47	2.5	2.5	2.5	515.0	X				206
JS30061412	Jun-30-14	1161-300614-ASB-JS-12	Outside Room # 19 ( Decon)	LV-5093	7:31	11:45	2.5	2.4	2.4	609.6	X				254
JS30061413	Jun-30-14	1161-300614-ASB-JS-13	Outside Room # 19 ( Decon)	LV-5093	13:17	14:34	2.5	2.5	2.5	192.5	X				77
JS30061414	Jun-30-14	1161-300614-ASB-JS-14	Outside Room # 2 & 20 ( Decon)	LV-5052	7:34	11:50	2.5	2.3	2.3	588.8	X				256
JS30061415	Jun-30-14	1161-300614-ASB-JS-15	Outside Room # 2 & 20 ( Decon)	LV-5052	13:22	16:48	2.5	2.5	2.5	515.0	X				206

Turn Around Time: Normal: 7 days <u>  X  </u>		Rush: 24 hours <u>          </u>		Rush: 16 hours <u>          </u>	
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:
Jose A Santos					Jose A Santos
Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:
Jun-30-14					Jun-30-14

*July 25-2014*





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-01-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> José A. Santos <b>Delivery By:</b> José A. Santos <b>Received By:</b> José A. Santos <b>Analyzed By:</b> José A. Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Ederick Caquias <b>Worker Name:</b> N/A <b>Worker Name:</b> N/A <b>Worker Name:</b> N/A	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 9 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-01-14 <b>Received Date:</b> Jul-01-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0813-0207-AS <b>Worker ID:</b> N/A <b>Worker ID:</b> N/A <b>Worker ID:</b> N/A
--	--

**Project Description:** Cleaning Rooms # 21.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-010714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-010714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-010714-ASB-JS-03	Ederick Caquias, Cleaning Room # 21	E	7:54	8:26	1.6	51.2	100	19	24.2	0.1820	0.0527	0.1820	< 0.0599
1161-010714-ASB-JS-04	Ederick Caquias, Cleaning Room # 21	PRCE	8:27	11:50	1.6	324.8	100	30.5	38.9	0.0461	0.0083	0.0461	
1161-010714-ASB-JS-05	Ederick Caquias, Cleaning Room # 21	PRCE	13:19	15:53	1.5	231.0	100	41.5	52.9	0.0881	0.0117	0.0881	
1161-010714-ASB-JS-06	Inside Area Room # 21	CE	7:55	11:51	2.5	590.0	100	38.5	49.0	0.0320	0.0046	0.0320	<
1161-010714-ASB-JS-07	Inside Area Room # 21	CE	13:20	15:54	2.3	354.2	100	33	42.0	0.0457	0.0076	0.0457	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b>	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b>
<b>Date:</b> Jul-01-14		<b>Date:</b>	





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions						<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo							
<b>Contact:</b> Melvin Feliciano						<b>Total Samples:</b> 9 <b>Job Number:</b> ENJ-1161							
<b>Phone / Fax/Email:</b> 787-426-1597						<b>Custody Record #:</b>							
<b>Sampling Date:</b> Jul-01-14 <b>Analytical Method:</b> NIOSH 7400						<b>Collected ID:</b> ASB-0912-0558-MS							
<b>Collected By:</b> José A. Santos						<b>Delivery Date:</b> Jul-01-14							
<b>Delivery By:</b> José A. Santos						<b>Received Date:</b> Jul-01-14							
<b>Received By:</b> José A. Santos						<b>AIHA Lab ID:</b> 199763							
<b>Analyzed By:</b> José A. Santos <b>Altol Chemical Environmental Laboratory, Inc.</b>						<b>Worker ID:</b> ASB-0813-0207-AS							
<b>Worker Name:</b> Ederick Caquias						<b>Worker ID:</b> N/A							
<b>Worker Name:</b> N/A						<b>Worker ID:</b> N/A							
<b>Worker Name:</b> N/A						<b>Worker ID:</b> N/A							
<b>Worker Name:</b> N/A						<b>Worker ID:</b> N/A							


  

<b>Project Description:</b> Cleaning Rooms # 21.													
--	--	--	--	--	--	--	--	--	--	--	--	--	--

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-010714-ASB-JS-08	Outside Room # 21 ( Decon)	OS	7:56	11:52	2.5	590.0	100	11	14.0	0.0091	0.0046	0.0091	
1161-010714-ASB-JS-09	Outside Room # 21 ( Decon)	OS	13:21	15:55	2.4	369.6	100	9	11.5	0.0119	0.0073	0.0119	

*MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.*

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b>	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b> 
<b>Date:</b> Jul-01-14		<b>Date:</b>	July-25-2014





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359  
CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE \_\_\_\_ OF \_\_\_\_

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>José A. Santos</u> <u>ASB-0912-0558-MS</u> <b>Analized By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>9</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>Ederick Caquias</u> <b>Worker ID:</b> <u>ASB-0813-0207-AS</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u>
--	--

**Project Description:** Cleaning Rooms # 21.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS01071401	Jul-01-14	1161-010714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---
JS01071402	Jul-01-14	1161-010714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---
JS01071403	Jul-01-14	1161-010714-ASB-JS-03	Ederick Caquias, Cleaning Room # 21	LV-6124	7:54	8:26	1.6	1.6	1.6	51.2	X			32
JS01071404	Jul-01-14	1161-010714-ASB-JS-04	Ederick Caquias, Cleaning Room # 21	LV-6124	8:27	11:50	1.6	1.6	1.6	324.8	X			203
JS01071405	Jul-01-14	1161-010714-ASB-JS-05	Ederick Caquias, Cleaning Room # 21	LV-6124	13:19	15:53	1.6	1.5	1.5	231.0	X			154
JS01071406	Jul-01-14	1161-010714-ASB-JS-06	Inside Area Room # 21	LV-5089	7:55	11:51	2.5	2.5	2.5	590.0	X			236
JS01071407	Jul-01-14	1161-010714-ASB-JS-07	Inside Area Room # 21	LV-5089	13:20	15:54	2.5	2.3	2.3	354.2	X			154
JS01071408	Jul-01-14	1161-010714-ASB-JS-08	Outside Room # 21 ( Decon)	LV-5093	7:56	11:52	2.5	2.5	2.5	590.0	X			236
JS01071409	Jul-01-14	1161-010714-ASB-JS-09	Outside Room # 21 ( Decon)	LV-5093	13:21	15:55	2.5	2.4	2.4	369.6	X			154

**Turn Around Time:** Normal: 7 days   X   Rush: 24 hours \_\_\_\_\_ Rush: 16 hours \_\_\_\_\_

Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
José A. Santos						José A. Santos
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-01-14						Jul-01-14

*July-25-2014*





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359  
FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

Customer Name: Homeca Recycling and Demolitions	Project Name: Esc Jorge Lucas Valdivieso 1 Unidad
Contact: Norma Collazo	Total Samples: 6 Job Number: ENJ-1161
Phone / Fax/Email: 787-373-6722	Custody Record #:
Sampling Date: Jul-04-14 Analytical Method: NIOSH 7400	Collected ID: ASB-0912-0558-MS
Collected By: Jose A Santos	Delivery Date: Jun-4-14
Delivery By: Jose A Santos	Received Date: Jun-4-14
Received By: Jose A Santos	AIHA Lab ID: 199763
Analyzed By: Jose A Santos Altol Chemical Environmental Laboratory, Inc.	Worker ID: N/A
Worker Name: N/A	Worker ID: N/A
Worker Name: N/A	Worker ID: N/A
Worker Name: N/A	Worker ID: N/A

Project Description: Backgrounds Collected in the following areas: Room # 1, 15 .

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-040714-ASB-JS-01	Field Blank I	FB											
1161-040714-ASB-JS-02	Field Blank II	FB											
1161-040714-ASB-JS-03	Background Collected in room # 1 ( East)	BG	9:05	11:05	10.0	1200.0	100	47.6	60.6	0.0195	0.0023	0.0195	<
1161-040714-ASB-JS-04	Background Collected in room # 1 ( West)	BG	9:06	11:06	10.0	1200.0	100	52.5	66.9	0.0215	0.0023	0.0215	
1161-040714-ASB-JS-05	Background Collected in room # 15 ( East)	BG	9:18	11:18	10.0	1200.0	100	37.5	47.8	0.0153	0.0023	0.0153	
1161-040714-ASB-JS-06	Background Collected in room # 15 ( West)	BG	9:19	11:20	10.0	1210.0	100	37.5	47.8	0.0152	0.0022	0.0152	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

Reported By: Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787 507-1627	Signature:	Verified By: Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	Signature:
Date: Jul-04-14		Date:	July 25 - 2014





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Norma Collazo</u> <b>Phone / Fax/Email:</b> <u>787-373-6722</u> <b>Collected By:</b> <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analized By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>Esc Jorge Lucas Valdivieso 1 Unidad</u> <b>Total Samples:</b> <u>6</u> <b>Job Number:</b> <u>ENJ 1161</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u>
--	--

**Project Description:** Backgrounds Collected In the following areas: Room # 1, 15 .

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lea Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS04071401	Jul-04-14	1161-040714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---
JS04071402	Jul-04-14	1161-040714-ASB-JS-02	Field Blank II	-----	----		----	----	----	---	X			---
JS04071403	Jul-04-14	1161-040714-ASB-JS-03	Background Collected in room # 1 ( East)	HV-6271	9:05	11:05	10.0	10.0	10.0	1200.0	X			120
JS04071404	Jul-04-14	1161-040714-ASB-JS-04	Background Collected in room # 1 ( West)	HV-5944	9:06	11:06	10.0	10.0	10.0	1200.0	X			120
JS04071405	Jul-04-14	1161-040714-ASB-JS-05	Background Collected in room # 15 ( East)	HV-4254	9:18	11:18	10.0	10.0	10.0	1200.0	X			120
JS04071406	Jul-04-14	1161-040714-ASB-JS-06	Background Collected in room # 15 ( West)	HV-4256	9:19	11:20	10.0	10.0	10.0	1210.0	X			121

**Turn Around Time:** Normal: 7 days   X        Rush: 24 hours                 Rush: 16 hours           

Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos
Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:
Jul-04-14						July-25-14





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-07-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> José A Santos <b>Delivery By:</b> José A Santos <b>Received By:</b> José A Santos <b>Analyzed By:</b> José A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> José E Santiago <b>Worker Name:</b> Eliceo Caraballo <b>Worker Name:</b> Geovanie González <b>Worker Name:</b> N/A							<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 19 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-07-14 <b>Received Date:</b> Jul-07-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0913-0333-AW <b>Worker ID:</b> ASB-1213-0505-AW <b>Worker ID:</b> ASB-0414-0118-AW <b>Worker ID:</b> N/A						
<b>Project Description:</b> Cleaning Rooms # 5, 17 Y 16.													
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-070714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-070714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-070714-ASB-JS-03	José E Santiago, Cleaning Room # 5	E	7:24	8:00	1.6	57.6	100	3	3.8	0.0255	0.0469	< 0.0469	< 0.0148
1161-070714-ASB-JS-04	José E Santiago, Cleaning Room # 5	PRCE	8:01	11:50	1.6	366.4	100	6.5	8.3	0.0087	0.0074	0.0087	
1161-070714-ASB-JS-05	José E Santiago, Cleaning Room # 5	PRCE	13:16	17:05	1.5	343.5	100	10.5	13.4	0.0150	0.0079	0.0150	
1161-070714-ASB-JS-06	Eliceo Caraballo, Cleaning Room # 17	PRCE	7:27	11:53	1.6	425.6	100	14.5	18.5	0.0167	0.0063	0.0167	0.0164
1161-070714-ASB-JS-07	Eliceo Caraballo, Cleaning Room # 17	PRCE	13:19	17:10	1.5	346.5	100	10.5	13.4	0.0149	0.0078	0.0149	
MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.													
<b>Reported By:</b> José A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627			<b>Signature:</b>		<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229			<b>Signature:</b>					
<b>Date:</b> Jul-07-14					<b>Date:</b>								






# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-07-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> José A Santos <b>Delivery By:</b> José A Santos <b>Received By:</b> José A Santos <b>Analyzed By:</b> José A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> José E Santiago <b>Worker Name:</b> Eliceo Caraballo <b>Worker Name:</b> Geovanie González <b>Worker Name:</b> N/A						<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 19 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-07-14 <b>Received Date:</b> Jul-07-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0913-0333-AW <b>Worker ID:</b> ASB-1213-0505-AW <b>Worker ID:</b> ASB-0414-0118-AW <b>Worker ID:</b> N/A							
<b>Project Description:</b> Cleaning Rooms # 5 ,17 Y 16.													
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-070714-ASB-JS-08	Geovanie González,Cleaning Room # 16	PRCE	7:30	11:55	1.6	424.0	100	15.5	19.7	0.0179	0.0064	0.0179	< 0.0099
1161-070714-ASB-JS-09	Geovanie González,Cleaning Room # 16	PRCE	13:22	17:13	1.4	323.4	100	19.5	24.8	0.0296	0.0083	0.0296	
1161-070714-ASB-JS-10	Inside Room # 5	CE	7:25	11:51	2.5	665.0	100	13	16.6	0.0096	0.0041	0.0096	
1161-070714-ASB-JS-11	Inside Room # 5	CE	13:17	17:06	2.3	526.7	100	9	11.5	0.0084	0.0051	0.0084	
1161-070714-ASB-JS-12	Inside Room # 17	CE	7:28	11:54	2.5	665.0	100	15	19.1	0.0111	0.0041	0.0111	
1161-070714-ASB-JS-13	Inside Room # 17	CE	13:20	17:11	2.4	554.4	100	17	21.7	0.0150	0.0049	0.0150	
1161-070714-ASB-JS-14	Inside Room # 16	CE	7:31	11:56	2.5	662.5	100	17.5	22.3	0.0130	0.0041	0.0130	
MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.													
<b>Reported By:</b> José A Santos Environmental Technician <a href="mailto:jose.santos@altolenterprises.com">jose.santos@altolenterprises.com</a> Phone: 787-507-1627			<b>Signature:</b>			<b>Verified By:</b> Carlos Ocasio Altol Operation Manager <a href="mailto:carlos.ocasio@altolenterprises.com">carlos.ocasio@altolenterprises.com</a> Phone: 787-835-4242 / 4229			<b>Signature:</b> 				
<b>Date:</b> Jul-07-14			<b>Date:</b>			July-25-2014							





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-07-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> José A Santos <b>Delivery By:</b> José A Santos <b>Received By:</b> José A Santos <b>Analyzed By:</b> José A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> José E Santiago <b>Worker Name:</b> Eliceo Caraballo <b>Worker Name:</b> Geovanie González <b>Worker Name:</b> N/A						<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 19 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-07-14 <b>Received Date:</b> Jul-07-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0913-0333-AW <b>Worker ID:</b> ASB-1213-0505-AW <b>Worker ID:</b> ASB-0414-0118-AW <b>Worker ID:</b> N/A					
<b>Project Description:</b> Cleaning Rooms # 5 ,17 Y 16.											

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-070714-ASB-JS-15	Inside Room # 5	OS	13:23	17:15	2.0	464.0	100	14	17.8	0.0148	0.0058	0.0148	
1161-070714-ASB-JS-16	Outside Room # 5 ( Decom )	OS	7:26	11:52	2.5	665.0	100	4	5.1	0.0030	0.0041	0.0041	
1161-070714-ASB-JS-17	Outside Room # 5 ( Decom )	OS	13:18	17:08	2.3	529.0	100	3	3.8	0.0028	0.0051	0.0051	
1161-070714-ASB-JS-18	Outside Rooms # 16 & 17 ( Decom )	OS	7:29	11:57	2.5	670.0	100	5.5	7.0	0.0040	0.0040	0.0040	
1161-070714-ASB-JS-19	Outside Rooms # 16 & 17 ( Decom )	OS	13:21	17:18	2.3	545.1	100	6	7.6	0.0054	0.0050	0.0054	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal  
 T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> José A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b>   	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b>   
<b>Date:</b>		<b>Date:</b> July-25-2014	





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

Customer Name: <b>Homeca Recycling and Demolitions</b>	Project Name: <b>1 ra Unidad Esc Jorge Lucas Valdiviezo</b>	
Contact: <b>Melvin Feliciano</b>	Total Samples: <b>19</b>	Job Number: <b>ENJ-1161</b>
Phone / Fax/Email: <b>787-426-1597</b>	Worker Name: <b>José E Santiago</b>	Worker ID: <b>ASB-0913-0333-AW</b>
Collected By: <b>José A Santos</b> <b>ASB-0912-0558-MS</b>	Worker Name: <b>Eliceo Caraballo</b>	Worker ID: <b>ASB-1213-0505-AW</b>
Analyzed By Lab: <b>Altol Chemical Environmental Laboratory, Inc.</b>	Worker Name: <b>Geovanie González</b>	Worker ID: <b>ASB-0414-0118-AW</b>
AIHA Lab ID: <b>199763</b>	Worker Name: <b>N/A</b>	Worker ID: <b>N/A</b>

Project Description: Cleaning Rooms # 5 ,17 Y 16.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS07071401	Jul-07-14	1161-070714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---
JS07071402	Jul-07-14	1161-070714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---
JS07071403	Jul-07-14	1161-070714-ASB-JS-03	José E Santiago, Cleaning Room # 5	LV-5087	7:24	8:00	1.6	1.6	1.6	57.6	X			36
JS07071404	Jul-07-14	1161-070714-ASB-JS-04	José E Santiago, Cleaning Room # 5	LV-5087	8:01	11:50	1.6	1.6	1.6	366.4	X			229
JS07071405	Jul-07-14	1161-070714-ASB-JS-05	José E Santiago, Cleaning Room # 5	LV-5087	13:16	17:05	1.6	1.5	1.5	343.5	X			229
JS07071406	Jul-07-14	1161-070714-ASB-JS-06	Eliceo Caraballo, Cleaning Room # 17	LV-6124	7:27	11:53	1.6	1.6	1.6	425.6	X			266
JS07071407	Jul-07-14	1161-070714-ASB-JS-07	Eliceo Caraballo, Cleaning Room # 17	LV-6124	13:19	17:10	1.6	1.5	1.5	346.5	X			231
JS07071408	Jul-07-14	1161-070714-ASB-JS-08	Geovanie González, Cleaning Room # 16	LV-5093	7:30	11:55	1.6	1.6	1.6	424.0	X			265
JS07071409	Jul-07-14	1161-070714-ASB-JS-09	Geovanie González, Cleaning Room # 16	LV-5093	13:22	17:13	1.6	1.4	1.4	323.4	X			231

Turn Around Time: Normal: 7 days <u>  X  </u>		Rush: 24 hours _____		Rush: 16 hours _____		
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
José A Santos						José A Santos
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-07-14						Jul-07-14

July 25-2014





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>José A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analyzed By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>19</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>José E Santiago</u> <b>Worker ID:</b> <u>ASB-0913-0333-AW</u> <b>Worker Name:</b> <u>Eliceo Caraballo</u> <b>Worker ID:</b> <u>ASB-1213-0505-AW</u> <b>Worker Name:</b> <u>Geovanie González</u> <b>Worker ID:</b> <u>ASB-0414-0118-AW</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u>
---	--

**Project Description:** Cleaning Rooms # 5 ,17 Y 16.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos			Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM	Air		
JS07071410	Jul-07-14	1161-070714-ASB-JS-10	Inside Room # 5	LV-5057	7:25	11:51	2.5	2.5	2.5	665.0	X				266
JS07071411	Jul-07-14	1161-070714-ASB-JS-11	Inside Room # 5	LV-5057	13:17	17:06	2.5	2.3	2.3	526.7	X				229
JS07071412	Jul-07-14	1161-070714-ASB-JS-12	Inside Room # 17	LV-2019	7:28	11:54	2.5	2.5	2.5	665.0	X				266
JS07071413	Jul-07-14	1161-070714-ASB-JS-13	Inside Room # 17	LV-2019	13:20	17:11	2.5	2.4	2.4	554.4	X				231
JS07071414	Jul-07-14	1161-070714-ASB-JS-14	Inside Room # 16	LV-5052	7:31	11:56	2.5	2.5	2.5	662.5	X				265
JS07071415	Jul-07-14	1161-070714-ASB-JS-15	Inside Room # 16	LV-5052	13:23	17:15	2.5	2.0	2.0	464.0	X				232
JS07071416	Jul-07-14	1161-070714-ASB-JS-16	Outside Room # 5 ( Decom)	LV-2022	7:26	11:52	2.5	2.5	2.5	665.0	X				266
JS07071417	Jul-07-14	1161-070714-ASB-JS-17	Outside Room # 5 ( Decom)	LV-2022	13:18	17:08	2.5	2.3	2.3	529.0	X				230
JS07071418	Jul-07-14	1161-070714-ASB-JS-18	Outside Rooms # 16 & 17(Decom)	LV-2072	7:29	11:57	2.5	2.5	2.5	670.0	X				268

<b>Turn Around Time: Normal: 7 days</b> <u>X</u>				<b>Rush: 24 hours</b> _____				<b>Rush: 16 hours</b> _____			
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:					
José A Santos						José A Santos <i>[Signature]</i>					
Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:					
Jul-07-14						Jul-07-14					

*July 25-14*





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>José A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analyzed By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>19</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>José E Santiago</u> <b>Worker ID:</b> <u>ASB-0913-0333-AW</u> <b>Worker Name:</b> <u>Eliceo Caraballo</u> <b>Worker ID:</b> <u>ASB-1213-0505-AW</u> <b>Worker Name:</b> <u>Geovanie González</u> <b>Worker ID:</b> <u>ASB-0414-0118-AW</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u>
<b>Project Description:</b> <u>Cleaning Rooms # 5 ,17 Y 16.</u>	

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS07071419	Jul-07-14	1161-070714-ASB-JS-19	Outside Rooms # 16 & 17(Decom)	LV-2072	13:21	17:18	2.5	2.3	2.3	545.1	X			237

<b>Turn Around Time: Normal: 7 days</b> <u>  X  </u>				<b>Rush: 24 hours</b> <u>          </u>				<b>Rush: 16 hours</b> <u>          </u>					
Sampling Collected by:		Relinquished by:		Received by:		Relinquished by:		Received by:		Delivery to Lab by:		Received at Lab by:	
José A Santos												José A Santos <i>[Signature]</i>	
Date:	Time:	Date:	Time:	Date:	Time:	Date:	Time:	Date:	Time:	Date:	Time:	Date:	Time:
Jul-07-14												Jul-07-14	

*July-25-14*





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions					<b>Project Name:</b> Esc Jorge Lucas Valdivieso 1 Unidad								
<b>Contact:</b> Norma Collazo					<b>Total Samples:</b> 6 <b>Job Number:</b> ENJ-1161								
<b>Phone / Fax/Email:</b> 787-373-6722					<b>Custody Record #:</b>								
<b>Sampling Date:</b> Jul-07-14 <b>Analytical Method:</b> NIOSH 7400					<b>Collected ID:</b> ASB-0912-0558-MS								
<b>Collected By:</b> José A Santos					<b>Delivery Date:</b> Jun-7-14								
<b>Delivery By:</b> José A Santos					<b>Received Date:</b> Jun-7-14								
<b>Received By:</b> José A Santos					<b>AIHA Lab ID:</b> 199763								
<b>Analyzed By:</b> José A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b>					<b>Worker ID:</b> N/A								
<b>Worker Name:</b> N/A					<b>Worker ID:</b> N/A								
<b>Worker Name:</b> N/A					<b>Worker ID:</b> N/A								
<b>Worker Name:</b> N/A					<b>Worker ID:</b> N/A								
<b>Worker Name:</b> N/A					<b>Worker ID:</b> N/A								

<b>Project Description:</b> Backgrounds Collected in the following areas: Room # 14, 12 .													
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-070714-ASB-JS-01	Field Blank I	FB											
1161-070714-ASB-JS-02	Field Blank II	FB											
1161-070714-ASB-JS-03	Background Collected in room # 14 ( East)	BG	13:32	16:40	10.0	1880.0	100	47.6	60.6	0.0124	0.0014	0.0124	<
1161-070714-ASB-JS-04	Background Collected in room # 14 ( West)	BG	13:33	16:41	10.0	1880.0	100	42.5	54.1	0.0111	0.0014	0.0111	
1161-070714-ASB-JS-05	Background Collected in room # 12 ( East)	BG	13:36	16:43	10.0	1870.0	100	40.5	51.6	0.0106	0.0014	0.0106	
1161-070714-ASB-JS-06	Background Collected in room # 12 ( West)	BG	13:37	16:44	10.0	1870.0	100	32	40.8	0.0084	0.0014	0.0084	
<b>MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.</b>													
<b>Reported By:</b> José A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787 507-1627		<b>Signature:</b>		<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229		<b>Signature:</b>							
<b>Date:</b> Jul-07-14				<b>Date:</b>		July-25-2014							





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Norma Collazo</u> <b>Phone / Fax/Email:</b> <u>787-373-6722</u> <b>Collected By:</b> <u>José A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analyzed By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>Esc Jorge Lucas Valdivieso 1 Unidad</u> <b>Total Samples:</b> <u>6</u> <b>Job Number:</b> <u>ENJ 1161</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u>
--	--

**Project Description:** Backgrounds Collected In the following areas: Room # 14, 12 .

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lea Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS07071401	Jul-07-14	1161-070714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---
JS07071402	Jul-07-14	1161-070714-ASB-JS-02	Field Blank II	-----	----		----	----	----	---	X			---
JS07071403	Jul-07-14	1161-070714-ASB-JS-03	Background Collected in room # 14 ( East)	HV-6271	13:32	16:40	10.0	10.0	10.0	1880.0	X			188
JS07071404	Jul-07-14	1161-070714-ASB-JS-04	Background Collected in room # 14 ( West)	HV-5944	13:33	16:41	10.0	10.0	10.0	1880.0	X			188
JS07071405	Jul-07-14	1161-070714-ASB-JS-05	Background Collected in room # 12 ( East)	HV-4254	13:36	16:43	10.0	10.0	10.0	1870.0	X			187
JS07071406	Jul-07-14	1161-070714-ASB-JS-06	Background Collected in room # 12 ( West)	HV-4256	13:37	16:44	10.0	10.0	10.0	1870.0	X			187

<b>Turn Around Time: Normal: 7 days</b> <u>  X  </u>				<b>Rush: 24 hours</b> _____		<b>Rush: 16 hours</b> _____	
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:	
José A Santos						José A Santos	
Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	
Jul-07-14						Jul-25-14	






# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-08-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> José A Santos <b>Delivery By:</b> José A Santos <b>Received By:</b> José A Santos <b>Analyzed By:</b> José A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Ederick Caquíás <b>Worker Name:</b> Héctor Montañez <b>Worker Name:</b> N/A <b>Worker Name:</b> N/A							<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 13 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-08-14 <b>Received Date:</b> Jul-08-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0813-0297-AW <b>Worker ID:</b> ASB-1013-0416-AW <b>Worker ID:</b> N/A <b>Worker ID:</b> N/A						
<b>Project Description:</b> Cleaning Rooms # 1, 15.													
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-080714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-080714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-080714-ASB-JS-03	Ederick Caquíás, Cleaning Room # 1	E	8:02	8:32	1.6	48.0	100	6.5	8.3	0.0664	0.0562	0.0664	< 0.0267
1161-080714-ASB-JS-04	Ederick Caquíás, Cleaning Room # 1	PRCE	8:33	11:50	1.6	315.2	100	15.5	19.7	0.0241	0.0086	0.0241	
1161-080714-ASB-JS-05	Ederick Caquíás, Cleaning Room # 1	PRCE	13:20	17:45	1.5	397.5	100	18.5	23.6	0.0228	0.0068	0.0228	
1161-080714-ASB-JS-06	Héctor Montañez, Cleaning Room # 15	PRCE	8:05	11:56	1.6	369.6	100	14.5	18.5	0.0192	0.0073	0.0192	0.0222
1161-080714-ASB-JS-07	Héctor Montañez, Cleaning Room # 15	PRCE	13:28	17:48	1.5	390.0	100	19	24.2	0.0239	0.0069	0.0239	
MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T = Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL = Clearance. E = Excursion.													
<b>Reported By:</b> José A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627			<b>Signature:</b>			<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229			<b>Signature:</b> 				
<b>Date:</b> Jul-08-14						<b>Date:</b> July 25 2014							





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-08-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> José A Santos <b>Delivery By:</b> José A Santos <b>Received By:</b> José A Santos <b>Analyzed By:</b> José A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Ederick Caquías <b>Worker Name:</b> Héctor Montañez <b>Worker Name:</b> N/A <b>Worker Name:</b> N/A	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 13 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-08-14 <b>Received Date:</b> Jul-08-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0813-0297-AW <b>Worker ID:</b> ASB-1013-0416-AW <b>Worker ID:</b> N/A <b>Worker ID:</b> N/A
--	--

**Project Description:** Cleaning Rooms # 1, 15 .

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-080714-ASB-JS-08	Inside Room # 1	CE	8:03	11:52	2.0	458.0	100	17.5	22.3	0.0187	0.0059	0.0187	<
1161-080714-ASB-JS-09	Inside Room # 1	CE	13:21	17:46	2.0	530.0	100	20.5	26.1	0.0190	0.0051	0.0190	
1161-080714-ASB-JS-10	Inside Room # 15	CE	8:07	11:57	2.0	460.0	100	17	21.7	0.0181	0.0059	0.0181	
1161-080714-ASB-JS-11	Inside Room # 15	CE	13:29	17:50	2.0	522.0	100	16.5	21.0	0.0155	0.0052	0.0155	
1161-080714-ASB-JS-12	Outside Rooms # 1 & 15	OS	8:04	11:55	2.0	462.0	100	11.5	14.6	0.0122	0.0058	0.0122	
1161-080714-ASB-JS-13	Outside Rooms # 1 & 15	OS	13:24	17:56	2.0	544.0	100	8.5	10.8	0.0077	0.0050	0.0077	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal  
 T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> José A Santos Environmental Technician <a href="mailto:jose.santos@altolenterprises.com">jose.santos@altolenterprises.com</a> Phone: 787-507-1627	<b>Signature:</b>  	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager <a href="mailto:carlos.ocasio@altolenterprises.com">carlos.ocasio@altolenterprises.com</a> Phone: 787-835-4242 / 4229
<b>Date:</b> Jul-08-14	<b>Date:</b>	<b>Signature:</b>  July 25 2014





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>José A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analyzed By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>13</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>Ederick Caquíás</u> <b>Worker ID:</b> <u>ASB-0813-0297-AW</u> <b>Worker Name:</b> <u>Héctor Montañez</u> <b>Worker ID:</b> <u>ASB-1013-0416-AW</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u>
---	--

**Project Description:** Cleaning Rooms # 1, 15 .

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS08071401	Jul-08-14	1161-080714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---
JS08071402	Jul-08-14	1161-080714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---
JS08071403	Jul-08-14	1161-080714-ASB-JS-03	Ederick Caquíás, Cleaning Room # 1	LV-5087	8:02	8:32	1.6	1.6	1.6	48.0	X			30
JS08071404	Jul-08-14	1161-080714-ASB-JS-04	Ederick Caquíás, Cleaning Room # 1	LV-5087	8:33	11:50	1.6	1.6	1.6	315.2	X			197
JS08071405	Jul-08-14	1161-080714-ASB-JS-05	Ederick Caquíás, Cleaning Room # 1	LV-5087	13:20	17:45	1.6	1.5	1.5	397.5	X			265
JS08071406	Jul-08-14	1161-080714-ASB-JS-06	Héctor Montañez, Cleaning Room # 15	LV-6124	8:05	11:56	1.6	1.6	1.6	369.6	X			231
JS08071407	Jul-08-14	1161-080714-ASB-JS-07	Héctor Montañez, Cleaning Room # 15	LV-6124	13:28	17:48	1.6	1.5	1.5	390.0	X			260
JS08071408	Jul-08-14	1161-080714-ASB-JS-08	Inside Room # 1	LV-5093	8:03	11:52	2.0	2.0	2.0	458.0	X			229
JS08071409	Jul-08-14	1161-080714-ASB-JS-09	Inside Room # 1	LV-5093	13:21	17:46	2.0	2.0	2.0	530.0	X			265

<b>Turn Around Time: Normal:</b> <u>7 days</u> <input checked="" type="checkbox"/> <b>Rush:</b> <u>24 hours</u> <input type="checkbox"/> <b>Rush:</b> <u>16 hours</u> <input type="checkbox"/>						
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
José A Santos						José A Santos
Date: Jul-08-14	Time:	Date:	Time:	Date:	Time:	Date: Jul-08-14

July-25-2014





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE \_\_\_\_ OF \_\_\_\_

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>José A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analyzed By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>13</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>Ederick Caquías</u> <b>Worker ID:</b> <u>ASB-0813-0297-AW</u> <b>Worker Name:</b> <u>Héctor Montañez</u> <b>Worker ID:</b> <u>ASB-1013-0416-AW</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u>
---	--

**Project Description:** Cleaning Rooms # 1, 15 .

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS08071410	Jul-08-14	1161-080714-ASB-JS-10	Inside Room # 15	LV-5057	8:07	11:57	2.0	2.0	2.0	460.0	X			230
JS08071411	Jul-08-14	1161-080714-ASB-JS-11	Inside Room # 15	LV-5057	13:29	17:50	2.0	2.0	2.0	522.0	X			261
JS08071412	Jul-08-14	1161-080714-ASB-JS-12	Outside Rooms # 1 & 15	LV-2019	8:04	11:55	2.0	2.0	2.0	462.0	X			231
JS08071413	Jul-08-14	1161-080714-ASB-JS-13	Outside Rooms # 1 & 15	LV-2019	13:24	17:56	2.0	2.0	2.0	544.0	X			272

<b>Turn Around Time:</b> Normal: 7 days <u>  X  </u> Rush: 24 hours <u>      </u> Rush: 16 hours <u>      </u>							
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:	
José A Santos						José A Santos <i>llr</i>	
Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	
Jul-08-14						Jul-08-14	

*July 25-2014*





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-09-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Alexis J Rivera <b>Worker Name:</b> Jorge Torres <b>Worker Name:</b> Felix Valentin <b>Worker Name:</b> _____ 0	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 19 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-09-14 <b>Received Date:</b> Jul-09-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0414-0119-AW <b>Worker ID:</b> ASB-1213-0504-AW <b>Worker ID:</b> ASB-1013-0415-AW <b>Worker ID:</b> N/A
--	---

**Project Description:** Cleaning Rooms # 1,15,25 & 18 .

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-090714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-090714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-090714-ASB-JS-03	Alexis Joel, Cleaning Room # 15	E	8:15	8:35	1.6	32.0	100	7	8.9	0.1073	0.0844	0.1073	< 0.0186
1161-090714-ASB-JS-04	Alexis Joel, Cleaning Room # 15	PRCE	8:36	11:56	1.6	320.0	100	11	14.0	0.0169	0.0084	0.0169	
1161-090714-ASB-JS-05	Alexis Joel, Cleaning Room # 15	PRCE	13:21	17:10	1.5	343.5	100	10.5	13.4	0.0150	0.0079	0.0150	
1161-090714-ASB-JS-06	Jorge Torres, Cleaning Room # 1	PRCE	8:20	11:59	1.6	350.4	100	17	21.7	0.0238	0.0077	0.0238	< 0.0194
1161-090714-ASB-JS-07	Jorge Torres, Cleaning Room # 1	PRCE	13:25	17:20	1.5	352.5	100	12.5	15.9	0.0174	0.0077	0.0174	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b> _____	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b> <i>Carlos E. Ocasio</i>
<b>Date:</b> Jul-09-14		<b>Date:</b> <i>July 25-2014</i>	





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-09-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Alexis J Rivera <b>Worker Name:</b> Jorge Torres <b>Worker Name:</b> Felix Valentin <b>Worker Name:</b> _____ 0					<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 19 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-09-14 <b>Received Date:</b> Jul-09-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0414-0119-AW <b>Worker ID:</b> ASB-1213-0504-AW <b>Worker ID:</b> ASB-1013-0415-AW <b>Worker ID:</b> N/A									
<b>Project Description:</b> Cleaning Rooms # 1,15,25 & 18 .														
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)	
			START	STOP										
1161-090714-ASB-JS-08	Felix Valentin, Cleaning Room # 18	PRCE	8:30	12:02	1.6	339.2	100	31	39.5	0.0448	0.0080	0.0448	< 0.0198	
1161-090714-ASB-JS-09	Felix Valentin, Cleaning Room # 25	PRCE	13:28	17:25	1.4	331.8	100	22.5	28.7	0.0333	0.0081	0.0333		
1161-090714-ASB-JS-10	Inside Room # 15	CE	8:16	11:57	2.5	552.5	100	12	15.3	0.0107	0.0049	0.0107		
1161-090714-ASB-JS-11	Inside Room # 15	CE	13:22	17:11	2.3	526.7	100	8	10.2	0.0074	0.0051	0.0074		
1161-090714-ASB-JS-12	Inside Room # 1	CE	8:21	12:00	2.5	547.5	100	16.5	21.0	0.0148	0.0049	0.0148		
1161-090714-ASB-JS-13	Inside Room # 1	CE	13:26	17:21	2.4	564.0	100	18	22.9	0.0157	0.0048	0.0157		
1161-090714-ASB-JS-14	Inside Room # 18	CE	8:31	12:03	2.5	530.0	100	16	20.4	0.0148	0.0051	0.0148		
MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.														
<b>Reported By:</b> Jose A Santos Environmental Technician <a href="mailto:jose.santos@altolenterprises.com">jose.santos@altolenterprises.com</a> Phone: 787-507-1627			<b>Signature:</b> _____		<b>Verified By:</b> Carlos Ocasio Altol Operation Manager <a href="mailto:carlos.ocasio@altolenterprises.com">carlos.ocasio@altolenterprises.com</a> Phone: 787-835-4242 / 4229			<b>Signature:</b> <i>Carlos Ocasio</i>						
<b>Date:</b> Jul-09-14					<b>Date:</b> _____			<i>July 25 2014</i>						






# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-09-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Alexis J Rivera <b>Worker Name:</b> Jorge Torres <b>Worker Name:</b> Felix Valentin <b>Worker Name:</b> _____ 0						<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 19 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-09-14 <b>Received Date:</b> Jul-09-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0414-0119-AW <b>Worker ID:</b> ASB-1213-0504-AW <b>Worker ID:</b> ASB-1013-0415-AW <b>Worker ID:</b> N/A							
<b>Project Description:</b> Cleaning Rooms # 1,15,25 & 18 .													
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-090714-ASB-JS-15	Inside Room # 25	OS	13:29	17:26	2.0	474.0	100	15.5	19.7	0.0160	0.0057	0.0160	
1161-090714-ASB-JS-16	Outside Rooms # 1 & 15 ( Decom )	OS	8:17	11:58	2.5	552.5	100	7.5	9.6	0.0067	0.0049	0.0067	
1161-090714-ASB-JS-17	Outside Rooms # 1 & 15 ( Decom )	OS	13:23	17:23	2.3	552.0	100	5.5	7.0	0.0049	0.0049	0.0049	
1161-090714-ASB-JS-18	Outside Rooms # 18 & 25 ( Decom )	OS	8:32	12:04	2.5	530.0	100	27.5	35.0	0.0254	0.0051	0.0254	
1161-090714-ASB-JS-19	Outside Rooms # 18 & 25 ( Decom )	OS	13:30	17:35	2.3	563.5	100	22	28.0	0.0191	0.0048	0.0191	
MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.													
<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627			<b>Signature:</b> _____			<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229			<b>Signature:</b>  July-25-2014				
<b>Date:</b> _____						<b>Date:</b> _____							





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

Customer Name: <b>Homeca Recycling and Demolitions</b>	Project Name: <b>1 ra Unidad Esc Jorge Lucas Valdiviezo</b>
Contact: <b>Melvin Feliciano</b>	Total Samples: <b>19</b> Job Number: <b>ENJ-1161</b>
Phone / Fax/Email: <b>787-426-1597</b>	Worker Name: <b>Alexis J Rivera</b> Worker ID: <b>ASB-0414-0119-AW</b>
Collected By: <b>Jose A Santos</b> <b>ASB-0912-0558-MS</b>	Worker Name: <b>Jorge Torres</b> Worker ID: <b>ASB-1213-0504-AW</b>
Analyzed By Lab: <b>Altol Chemical Environmental Laboratory, Inc.</b>	Worker Name: <b>Felix Valentin</b> Worker ID: <b>ASB-1013-0415-AW</b>
AIHA Lab ID: <b>199763</b>	Worker Name: Worker ID: <b>N/A</b>

Project Description: Cleaning Rooms # 1,15,25 & 18 .

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS09071401	Jul-09-14	1161-090714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---
JS09071402	Jul-09-14	1161-090714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---
JS09071403	Jul-09-14	1161-090714-ASB-JS-03	Alexis Joel, Cleaning Room # 15	LV-5087	8:15	8:35	1.6	1.6	1.6	32.0	X			20
JS09071404	Jul-09-14	1161-090714-ASB-JS-04	Alexis Joel, Cleaning Room # 15	LV-5087	8:36	11:56	1.6	1.6	1.6	320.0	X			200
JS09071405	Jul-09-14	1161-090714-ASB-JS-05	Alexis Joel, Cleaning Room # 15	LV-5087	13:21	17:10	1.6	1.5	1.5	343.5	X			229
JS09071406	Jul-09-14	1161-090714-ASB-JS-06	Jorge Torres, Cleaning Room # 1	LV-6124	8:20	11:59	1.6	1.6	1.6	350.4	X			219
JS09071407	Jul-09-14	1161-090714-ASB-JS-07	Jorge Torres, Cleaning Room # 1	LV-6124	13:25	17:20	1.6	1.5	1.5	352.5	X			235
JS09071408	Jul-09-14	1161-090714-ASB-JS-08	Felix Valentin, Cleaning Room # 18	LV-5093	8:30	12:02	1.6	1.6	1.6	339.2	X			212
JS09071409	Jul-09-14	1161-090714-ASB-JS-09	Felix Valentin, Cleaning Room # 25	LV-5093	13:28	17:25	1.6	1.4	1.4	331.8	X			237

Turn Around Time: Normal: 7 days <u>  X  </u>		Rush: 24 hours _____		Rush: 16 hours _____		
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-09-14						Jul-09-14

*July 25 2014*





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analyzed By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>19</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>Alexis J Rivera</u> <b>Worker ID:</b> <u>ASB-0414-0119-AW</u> <b>Worker Name:</b> <u>Jorge Torres</u> <b>Worker ID:</b> <u>ASB-1213-0504-AW</u> <b>Worker Name:</b> <u>Felix Valentin</u> <b>Worker ID:</b> <u>ASB-1013-0415-AW</u> <b>Worker Name:</b> <b>Worker ID:</b> <u>N/A</u>
---	--

**Project Description:** Cleaning Rooms # 1,15,25 & 18 .

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS09071410	Jul-09-14	1161-090714-ASB-JS-10	Inside Room # 15	LV-5057	8:16	11:57	2.5	2.5	2.5	552.5	X			221
JS09071411	Jul-09-14	1161-090714-ASB-JS-11	Inside Room # 15	LV-5057	13:22	17:11	2.5	2.3	2.3	526.7	X			229
JS09071412	Jul-09-14	1161-090714-ASB-JS-12	Inside Room # 1	LV-2019	8:21	12:00	2.5	2.5	2.5	547.5	X			219
JS09071413	Jul-09-14	1161-090714-ASB-JS-13	Inside Room # 1	LV-2019	13:26	17:21	2.5	2.4	2.4	564.0	X			235
JS09071414	Jul-09-14	1161-090714-ASB-JS-14	Inside Room # 18	LV-5052	8:31	12:03	2.5	2.5	2.5	530.0	X			212
JS09071415	Jul-09-14	1161-090714-ASB-JS-15	Inside Room # 25	LV-5052	13:29	17:26	2.5	2.0	2.0	474.0	X			237
JS09071416	Jul-09-14	1161-090714-ASB-JS-16	Outside Rooms # 1 & 15 ( Decom )	LV-2022	8:17	11:58	2.5	2.5	2.5	552.5	X			221
JS09071417	Jul-09-14	1161-090714-ASB-JS-17	Outside Rooms # 1 & 15 ( Decom )	LV-2022	13:23	17:23	2.5	2.3	2.3	552.0	X			240
JS09071418	Jul-09-14	1161-090714-ASB-JS-18	Outside Rooms # 18 & 25 ( Area )	LV-2072	8:32	12:04	2.5	2.5	2.5	530.0	X			212

<b>Turn Around Time: Normal: 7 days</b> <u>  X  </u>		<b>Rush: 24 hours</b> _____		<b>Rush: 16 hours</b> _____	
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:
Jose A Santos					
Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:
Jul-09-14					Jul-09-14

July 25-2014





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analyzed By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>19</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>Alexis J Rivera</u> <b>Worker ID:</b> <u>ASB-0414-0119-AW</u> <b>Worker Name:</b> <u>Jorge Torres</u> <b>Worker ID:</b> <u>ASB-1213-0504-AW</u> <b>Worker Name:</b> <u>Felix Valentin</u> <b>Worker ID:</b> <u>ASB-1013-0415-AW</u> <b>Worker Name:</b> <b>Worker ID:</b> <u>N/A</u>
---	--

**Project Description:** Cleaning Rooms # 1,15,25 & 18 .

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS09071419	Jul-09-14	1161-090714-ASB-JS-19	Outside Rooms # 18 & 25 ( Area )	LV-2072	13:30	17:35	2.5	2.3	2.3	563.5	X			245

<b>Turn Around Time: Normal: 7 days</b> <u>  X  </u>				<b>Rush: 24 hours</b> <u>          </u>				<b>Rush: 16 hours</b> <u>          </u>			
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:					
Jose A Santos						Jose A Santos					
Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:					
Jul-09-14						Jul-09-14					

*July 25 2014*





**ALTOL ENVIRONMENTAL SERVICES, INC.**  
PO BOX 359 MERCEDITA, PR 00715-0359  
**FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS**

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-10-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Eliezer Caraballo <b>Worker Name:</b> Emmanuel Ramos <b>Worker Name:</b> Luis N Ortiz <b>Worker Name:</b> _____ 0	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 19 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-10-14 <b>Received Date:</b> Jul-10-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0614-0253-AW <b>Worker ID:</b> ASB-0913-0335-AW <b>Worker ID:</b> ASB-0414-0117-AW <b>Worker ID:</b> N/A
--	---

**Project Description:** Cleaning Rooms # 1,25,14, & 13.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-100714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-100714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-100714-ASB-JS-03	Eliezer Caraballo, Cleaning Room # 1	E	7:19	7:49	1.6	48.0	100	4.5	5.7	0.0460	0.0562	< 0.0562	< 0.0190
1161-100714-ASB-JS-04	Eliezer Caraballo, Cleaning Room # 1	PRCE	7:50	11:54	1.6	390.4	100	13	16.6	0.0163	0.0069	0.0163	
1161-100714-ASB-JS-05	Eliezer Caraballo, Cleaning Room # 1	PRCE	13:15	17:42	1.5	400.5	100	10.5	13.4	0.0129	0.0067	0.0129	
1161-100714-ASB-JS-06	Emmanuel Ramos, Cleaning Room # 14	PRCE	7:32	12:05	1.6	436.8	100	29	36.9	0.0326	0.0062	0.0326	0.0410
1161-100714-ASB-JS-07	Emmanuel Ramos, Cleaning Room # 14	PRCE	13:20	17:48	1.5	402.0	100	33	42.0	0.0403	0.0067	0.0403	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b> _____	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b> <i>Carlos Ocasio</i>  <i>July 25-2014</i>
<b>Date:</b> Jul-10-14		<b>Date:</b> _____	





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-10-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Eliezer Caraballo <b>Worker Name:</b> Emmanuel Ramos <b>Worker Name:</b> Luis N Ortiz <b>Worker Name:</b> _____ 0	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 19 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-10-14 <b>Received Date:</b> Jul-10-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0614-0253-AW <b>Worker ID:</b> ASB-0913-0335-AW <b>Worker ID:</b> ASB-0414-0117-AW <b>Worker ID:</b> N/A
--	---

**Project Description:** Cleaning Rooms # 1,25,14, & 13.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-100714-ASB-JS-08	Luis N Ortiz, Cleaning Room # 13	PRCE	7:36	12:07	1.6	433.6	100	22.5	28.7	0.0254	0.0062	0.0254	< 0.0144
1161-100714-ASB-JS-09	Luis N Ortiz, Cleaning Room # 13	PRCE	13:26	17:51	1.4	371.0	100	31.5	40.1	0.0416	0.0073	0.0416	
1161-100714-ASB-JS-10	Inside Room # 1	CE	7:22	11:55	2.5	682.5	100	13	16.6	0.0093	0.0040	0.0093	
1161-100714-ASB-JS-11	Inside Room # 1	CE	13:16	17:43	2.3	614.1	100	10	12.7	0.0080	0.0044	0.0080	
1161-100714-ASB-JS-12	Inside Room # 14	CE	7:33	12:06	2.5	682.5	100	26.5	33.8	0.0190	0.0040	0.0190	
1161-100714-ASB-JS-13	Inside Room # 14	CE	13:21	17:49	2.4	643.2	100	20.5	26.1	0.0156	0.0042	0.0156	
1161-100714-ASB-JS-14	Inside Room # 13	CE	7:37	12:08	2.5	677.5	100	23.5	29.9	0.0170	0.0040	0.0170	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal  
 T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b> _____	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b> July 25-2014
<b>Date:</b> Jul-10-14		<b>Date:</b> _____	





**ALTOL ENVIRONMENTAL SERVICES, INC.**  
 PO BOX 359 MERCEDITA, PR 00715-0359  
**FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS**

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-10-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Eliezer Caraballo <b>Worker Name:</b> Emmanuel Ramos <b>Worker Name:</b> Luis N Ortiz <b>Worker Name:</b> _____ 0	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 19 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-10-14 <b>Received Date:</b> Jul-10-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> _____ ASB-0614-0253-AW <b>Worker ID:</b> _____ ASB-0913-0335-AW <b>Worker ID:</b> _____ ASB-0414-0117-AW <b>Worker ID:</b> _____ N/A
--	---

**Project Description:** Cleaning Rooms # 1,25,14, & 13.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-100714-ASB-JS-15	Inside Room # 25	OS	13:27	17:52	2.0	530.0	100	18.5	23.6	0.0171	0.0051	0.0171	
1161-100714-ASB-JS-16	Outside Rooms # 1 & 15 ( Decom )	OS	7:23	11:57	2.5	685.0	100	6.5	8.3	0.0047	0.0039	0.0047	
1161-100714-ASB-JS-17	Outside Rooms # 1 & 15 ( Decom )	OS	13:18	17:44	2.3	611.8	100	8	10.2	0.0064	0.0044	0.0064	
1161-100714-ASB-JS-18	Outside Rooms # 18 & 25 ( Decom )	OS	7:34	12:10	2.5	690.0	100	8.5	10.8	0.0060	0.0039	0.0060	
1161-100714-ASB-JS-19	Outside Rooms # 18 & 25 ( Decom )	OS	13:29	17:54	2.3	609.5	100	13.5	17.2	0.0109	0.0044	0.0109	

*MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.*

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b> _____	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b> Date: <u>July 25-2014</u>
<b>Date:</b> _____		<b>Date:</b> _____	





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE \_\_\_\_ OF \_\_\_\_

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analyzed By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>19</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>Eliezer Caraballo</u> <b>Worker ID:</b> <u>ASB-0614-0253-AW</u> <b>Worker Name:</b> <u>Emmanuel Ramos</u> <b>Worker ID:</b> <u>ASB-0913-0335-AW</u> <b>Worker Name:</b> <u>Luis N Ortiz</u> <b>Worker ID:</b> <u>ASB-0414-0117-AW</u> <b>Worker Name:</b> <b>Worker ID:</b> <u>N/A</u>
---	--

**Project Description:** Cleaning Rooms # 1,25,14, & 13.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS10071401	Jul-10-14	1161-100714-ASB-JS-01	Field Blank I	*****	----	----	----	----	----	---	X			---
JS10071402	Jul-10-14	1161-100714-ASB-JS-02	Field Blank II	*****	----	----	----	----	----	---	X			---
JS10071403	Jul-10-14	1161-100714-ASB-JS-03	Eliezer Caraballo, Cleaning Room # 1	LV-6124	7:19	7:49	1.6	1.6	1.6	48.0	X			30
JS10071404	Jul-10-14	1161-100714-ASB-JS-04	Eliezer Caraballo, Cleaning Room # 1	LV-6124	7:50	11:54	1.6	1.6	1.6	390.4	X			244
JS10071405	Jul-10-14	1161-100714-ASB-JS-05	Eliezer Caraballo, Cleaning Room # 1	LV-6124	13:15	17:42	1.6	1.5	1.5	400.5	X			267
JS10071406	Jul-10-14	1161-100714-ASB-JS-06	Emmanuel Ramos, Cleaning Room # 14	LV-5087	7:32	12:05	1.6	1.6	1.6	436.8	X			273
JS10071407	Jul-10-14	1161-100714-ASB-JS-07	Emmanuel Ramos, Cleaning Room # 14	LV-5087	13:20	17:48	1.6	1.5	1.5	402.0	X			268
JS10071408	Jul-10-14	1161-100714-ASB-JS-08	Luis N Ortiz, Cleaning Room # 13	LV-5093	7:36	12:07	1.6	1.6	1.6	433.6	X			271
JS10071409	Jul-10-14	1161-100714-ASB-JS-09	Luis N Ortiz, Cleaning Room # 13	LV-5093	13:26	17:51	1.6	1.4	1.4	371.0	X			265

**Turn Around Time:** Normal: 7 days   X        Rush: 24 hours \_\_\_\_\_      Rush: 16 hours \_\_\_\_\_

Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos
Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:
Jul-10-14						Jul-10-14

July-25-2014





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

Customer Name: <b>Homeca Recycling and Demolitions</b>	Project Name: <b>1 ra Unidad Esc Jorge Lucas Valdiviezo</b>
Contact: <b>Melvin Feliciano</b>	Total Samples: <b>19</b> Job Number: <b>ENJ-1161</b>
Phone / Fax/Email: <b>787-426-1597</b>	Worker Name: <b>Eliezer Caraballo</b> Worker ID: <b>ASB-0614-0253-AW</b>
Collected By: <b>Jose A Santos</b> <b>ASB-0912-0558-MS</b>	Worker Name: <b>Emmanuel Ramos</b> Worker ID: <b>ASB-0913-0335-AW</b>
Analized By Lab: <b>Altol Chemical Environmental Laboratory, Inc.</b>	Worker Name: <b>Luis N Ortiz</b> Worker ID: <b>ASB-0414-0117-AW</b>
AIHA Lab ID: <b>199763</b>	Worker Name: Worker ID: <b>N/A</b>

Project Description: Cleaning Rooms # 1,25,14, & 13.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS10071410	Jul-10-14	1161-100714-ASB-JS-10	Inside Room # 1	LV-2022	7:22	11:55	2.5	2.5	2.5	682.5	X			273
JS10071411	Jul-10-14	1161-100714-ASB-JS-11	Inside Room # 1	LV-2022	13:16	17:43	2.5	2.3	2.3	614.1	X			267
JS10071412	Jul-10-14	1161-100714-ASB-JS-12	Inside Room # 14	LV-2019	7:33	12:06	2.5	2.5	2.5	682.5	X			273
JS10071413	Jul-10-14	1161-100714-ASB-JS-13	Inside Room # 14	LV-2019	13:21	17:49	2.5	2.4	2.4	643.2	X			268
JS10071414	Jul-10-14	1161-100714-ASB-JS-14	Inside Room # 13	LV-5052	7:37	12:08	2.5	2.5	2.5	677.5	X			271
JS10071415	Jul-10-14	1161-100714-ASB-JS-15	Inside Room # 13	LV-5052	13:27	17:52	2.5	2.0	2.0	530.0	X			265
JS10071416	Jul-10-14	1161-100714-ASB-JS-16	Outside Room # 1 ( Decom)	LV-6268	7:23	11:57	2.5	2.5	2.5	685.0	X			274
JS10071417	Jul-10-14	1161-100714-ASB-JS-17	Outside Room # 1 ( Decom)	LV-6268	13:18	17:44	2.5	2.3	2.3	611.8	X			266
JS10071418	Jul-10-14	1161-100714-ASB-JS-18	Outside Rooms # 14 & 13 ( Area )	LV-2072	7:34	12:10	2.5	2.5	2.5	690.0	X			276

Turn Around Time: Normal: 7 days <u>  X  </u>		Rush: 24 hours _____		Rush: 16 hours _____	
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:
Jose A Santos					
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-10-14					Jul-10-14

July-25-2014



**ALTOL ENVIRONMENTAL SERVICES, INC.**

PO BOX 359 MERCEDITA, PR 00715-0359

**CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)**

PAGE \_\_\_\_ OF \_\_\_\_

Customer Name: <b>Homeca Recycling and Demolitions</b>	Project Name: <b>1 ra Unidad Esc Jorge Lucas Valdiviezo</b>
Contact: <b>Melvin Feliciano</b>	Total Samples: <b>19</b> Job Number: <b>ENJ-1161</b>
Phone / Fax/Email: <b>787-426-1597</b>	Worker Name: <b>Eliezer Caraballo</b> Worker ID: <b>ASB-0614-0253-AW</b>
Collected By: <b>Jose A Santos</b> <b>ASB-0912-0558-MS</b>	Worker Name: <b>Emmanuel Ramos</b> Worker ID: <b>ASB-0913-0335-AW</b>
Analized By Lab: <b>Altol Chemical Environmental Laboratory, Inc.</b>	Worker Name: <b>Luis N Ortiz</b> Worker ID: <b>ASB-0414-0117-AW</b>
AIHA Lab ID: <b>199763</b>	Worker Name: Worker ID: <b>N/A</b>

Project Description: **Cleaning Rooms # 1,25,14, & 13.**

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS10071419	Jul-10-14	1161-100714-ASB-JS-19	Outside Rooms # 14 & 13 ( Area )	LV-2072	13:29	17:54	2.5	2.3	2.3	609.5	X			265

Turn Around Time: Normal: 7 days <u>  X  </u>		Rush: 24 hours <u>          </u>		Rush: 16 hours <u>          </u>		
Sampling Collected by: Jose A Santos	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by: Jose A Santos
Date: Jul-10-14	Time:	Date:	Time:	Date:	Time:	Date: Jul-10-14

July-25-2014





**ALTOL ENVIRONMENTAL SERVICES, INC.**  
PO BOX 359 MERCEDITA, PR 00715-0359  
**FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS**

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-11-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> José A Santos <b>Delivery By:</b> José A Santos <b>Received By:</b> José A Santos <b>Analyzed By:</b> José A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Emmanuel Ramos <b>Worker Name:</b> José E Santiago <b>Worker Name:</b> José L Sierra <b>Worker Name:</b> _____ 0	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 17 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-11-14 <b>Received Date:</b> Jul-11-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0913-0335-AW <b>Worker ID:</b> ASB-0913-0333-AW <b>Worker ID:</b> ASB-1113-0477-AW <b>Worker ID:</b> N/A
---	---

**Project Description:** Cleaning Rooms #,14,13 and 12.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-110714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-110714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-110714-ASB-JS-03	Emmanuel Ramos, Cleaning Room # 14	E	7:21	7:52	1.6	49.6	100	5.5	7.0	0.0544	0.0544	< 0.0544	< 0.0305
1161-110714-ASB-JS-04	Emmanuel Ramos, Cleaning Room # 14	PRCE	7:58	11:50	1.5	348.0	100	10.5	13.4	0.0148	0.0078	0.0148	
1161-110714-ASB-JS-05	Jose E Santiago, Cleaning Room # 13	PRCE	7:26	11:54	1.6	428.8	100	31	39.5	0.0355	0.0063	0.0355	0.0272
1161-110714-ASB-JS-06	Jose E Santiago, Cleaning Room # 13	PRCE	13:15	17:40	1.5	397.5	100	24	30.6	0.0296	0.0068	0.0296	
1161-110714-ASB-JS-07	Jose L Sierra, Cleaning Room # 12	PRCE	7:28	12:00	1.6	435.2	100	17	21.7	0.0192	0.0062	0.0192	0.0109

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b> _____	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b> July-25-2014
<b>Date:</b> Jul-11-14		<b>Date:</b> _____	





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo
<b>Contact:</b> Melvin Feliciano	<b>Total Samples:</b> 17 <b>Job Number:</b> ENJ-1161
<b>Phone / Fax/Email:</b> 787-426-1597	<b>Custody Record #:</b>
<b>Sampling Date:</b> Jul-11-14 <b>Analytical Method:</b> NIOSH 7400	<b>Collected ID:</b> ASB-0912-0558-MS
<b>Collected By:</b> José A Santos	<b>Delivery Date:</b> Jul-11-14
<b>Delivery By:</b> José A Santos	<b>Received Date:</b> Jul-11-14
<b>Received By:</b> José A Santos	<b>AIHA Lab ID:</b> 199763
<b>Analyzed By:</b> José A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b>	<b>Worker ID:</b> ASB-0913-0335-AW
<b>Worker Name:</b> Emmanuel Ramos	<b>Worker ID:</b> ASB-0913-0333-AW
<b>Worker Name:</b> José E Santiago	<b>Worker ID:</b> ASB-1113-0477-AW
<b>Worker Name:</b> José L Sierra	<b>Worker ID:</b> N/A
<b>Worker Name:</b>	

**Project Description:** Cleaning Rooms #,14,13 and 12.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-110714-ASB-JS-08	Jose L Sierra, Cleaning Room # 12	PRCE	13:24	17:48	1.4	369.6	100	13.5	17.2	0.0179	0.0073	0.0179	< 0.0099
1161-110714-ASB-JS-09	Inside Room # 14	CE	7:22	11:51	2.0	538.0	100	12	15.3	0.0109	0.0050	0.0109	
1161-110714-ASB-JS-10	Inside Room # 13	CE	7:27	11:55	2.0	536.0	100	24	30.6	0.0220	0.0050	0.0220	
1161-110714-ASB-JS-11	Inside Room # 13	CE	13:18	17:42	2.0	528.0	100	21.5	27.4	0.0200	0.0051	0.0200	
1161-110714-ASB-JS-12	Inside Room # 12	CE	7:29	11:57	2.0	536.0	100	15	19.1	0.0137	0.0050	0.0137	
1161-110714-ASB-JS-13	Inside Room # 12	CE	13:25	17:49	2.0	528.0	100	12	15.3	0.0111	0.0051	0.0111	
1161-110714-ASB-JS-14	Outside Rooms # 13 & 14 ( Decom)	OS	7:23	11:52	2.5	672.5	100	6.5	8.3	0.0047	0.0040	0.0047	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b>	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b>
<b>Date:</b> Jul-11-14		<b>Date:</b>	





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-11-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> José A Santos <b>Delivery By:</b> José A Santos <b>Received By:</b> José A Santos <b>Analyzed By:</b> José A Santos      Altol Chemical Environmental Laboratory, Inc. <b>Worker Name:</b> Emmanuel Ramos <b>Worker Name:</b> José E Santiago <b>Worker Name:</b> José L Sierra <b>Worker Name:</b> _____ 0							<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 17 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-11-14 <b>Received Date:</b> Jul-11-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> _____ ASB-0913-0335-AW <b>Worker ID:</b> _____ ASB-0913-0333-AW <b>Worker ID:</b> _____ ASB-1113-0477-AW <b>Worker ID:</b> _____ N/A						
<b>Project Description:</b> <u>Cleaning Rooms #,14,13 and 12.</u>													
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-110714-ASB-JS-15	Outside Room # 13 ( Decom )	OS	13:20	17:43	2.3	604.9	100	5	6.4	0.0041	0.0045	0.0045	
1161-110714-ASB-JS-16	Outside Room 12 ( Decom )	OS	7:31	12:03	2.5	680.0	100	6	7.6	0.0043	0.0040	0.0043	
1161-110714-ASB-JS-17	Outside Room 12 ( Decom )	OS	13:26	17:52	2.4	638.4	100	7.5	9.6	0.0058	0.0042	0.0058	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal  
 T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician <a href="mailto:jose.santos@altolenterprises.com">jose.santos@altolenterprises.com</a> Phone: 787-507-1627	<b>Signature:</b> _____  <b>Verified By:</b> Carlos Ocasio Altol Operation Manager <a href="mailto:carlos.ocasio@altolenterprises.com">carlos.ocasio@altolenterprises.com</a> Phone: 787-835-4242 / 4229	<b>Signature:</b>  <b>Date:</b> <u>July 25-2014</u>
--	---	---





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>José A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analyzed By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>17</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>Emmanuel Ramos</u> <b>Worker ID:</b> <u>ASB-0913-0335-AW</u> <b>Worker Name:</b> <u>José E Santiago</u> <b>Worker ID:</b> <u>ASB-0913-0333-AW</u> <b>Worker Name:</b> <u>José L Sierra</u> <b>Worker ID:</b> <u>ASB-1113-0477-AW</u> <b>Worker Name:</b> _____ <b>Worker ID:</b> <u>N/A</u>
---	---

**Project Description:** Cleaning Rooms #,14,13 and 12.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS11071401	Jul-11-14	1161-110714-ASB-JS-01	Field Blank I	*****	----	----	----	----	----	---	X			---
JS11071402	Jul-11-14	1161-110714-ASB-JS-02	Field Blank II	*****	----	----	----	----	----	---	X			---
JS11071403	Jul-11-14	1161-110714-ASB-JS-03	Emmanuel Ramos, Cleaning Room # 14	LV-6124	7:21	7:52	1.6	1.6	1.6	49.6	X			31
JS11071404	Jul-11-14	1161-110714-ASB-JS-04	Emmanuel Ramos, Cleaning Room # 14	LV-6124	7:58	11:50	1.6	1.5	1.5	348.0	X			232
JS11071405	Jul-11-14	1161-110714-ASB-JS-05	Jose E Santiago, Cleaning Room # 13	LV-5087	7:26	11:54	1.6	1.6	1.5	402.0	X			268
JS11071406	Jul-11-14	1161-110714-ASB-JS-06	Jose E Santiago, Cleaning Room # 13	LV-5087	13:15	17:40	1.6	1.4	1.4	371.0	X			265
JS11071407	Jul-11-14	1161-110714-ASB-JS-07	Jose L Sierra, Cleaning Room # 12	LV-5093	7:28	12:00	1.6	1.6	1.6	435.2	X			272
JS11071408	Jul-11-14	1161-110714-ASB-JS-08	Jose L Sierra, Cleaning Room # 12	LV-5093	13:24	17:48	1.6	1.4	1.4	369.6	X			264
JS11071409	Jul-11-14	1161-110714-ASB-JS-09	Inside Room # 14	LV-2022	7:22	11:51	2.0	2.0	2.0	538.0	X			269

<b>Turn Around Time: Normal:</b> 7 days <u>  X  </u>				<b>Rush:</b> 24 hours _____				<b>Rush:</b> 16 hours _____			
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:					
José A Santos						José A Santos					
Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____					
Jul-11-14						Jul-11-14					

*July 25 2014*





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359  
CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE \_\_\_\_ OF \_\_\_\_

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>José A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analized By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>17</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>Emmanuel Ramos</u> <b>Worker ID:</b> <u>ASB-0913-0335-AW</u> <b>Worker Name:</b> <u>José E Santiago</u> <b>Worker ID:</b> <u>ASB-0913-0333-AW</u> <b>Worker Name:</b> <u>José L Sierra</u> <b>Worker ID:</b> <u>ASB-1113-0477-AW</u> <b>Worker Name:</b> _____ <b>Worker ID:</b> <u>N/A</u>
---	---

**Project Description:** Cleaning Rooms #,14,13 and 12.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS11071410	Jul-11-14	1161-110714-ASB-JS-10	Inside Room # 13	LV-2019	7:27	11:55	2.0	2.0	2.0	536.0	X			268
JS11071411	Jul-11-14	1161-110714-ASB-JS-11	Inside Room # 13	LV-2019	13:18	17:42	2.0	2.0	2.0	528.0	X			264
JS11071412	Jul-11-14	1161-110714-ASB-JS-12	Inside Room # 12	LV-5052	7:29	11:57	2.0	2.0	2.0	536.0	X			268
JS11071413	Jul-11-14	1161-110714-ASB-JS-13	Inside Room # 12	LV-5052	13:25	17:49	2.0	2.0	2.0	528.0	X			264
JS11071414	Jul-11-14	1161-110714-ASB-JS-14	Outside Rooms # 13 & 14 ( Decom )	LV-6268	7:23	11:52	2.5	2.5	2.5	672.5	X			269
JS11071415	Jul-11-14	1161-110714-ASB-JS-15	Outside Rooms # 13 ( Decom )	LV-6268	13:20	17:43	2.5	2.3	2.3	604.9	X			263
JS11071416	Jul-11-14	1161-110714-ASB-JS-16	Outside Room 12 ( Decom )	LV-5089	7:31	12:03	2.5	2.5	2.5	680.0	X			272
JS11071417	Jul-11-14	1161-110714-ASB-JS-17	Outside Room 12 ( Decom )	LV-5089	13:26	17:52	2.5	2.4	2.4	638.4	X			266

<b>Turn Around Time: Normal: 7 days</b> <u>  X  </u> <b>Rush: 24 hours</b> _____ <b>Rush: 16 hours</b> _____							
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:	
José A Santos						José A Santos	
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	
Jul-11-14						Jul-11-14	

July 25-2014





**ALTOL ENVIRONMENTAL SERVICES, INC.**  
PO BOX 359 MERCEDITA, PR 00715-0359  
**FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS**

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-14-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Luis N Ortiz <b>Worker Name:</b> Felix Valentin <b>Worker Name:</b> _____ 0 <b>Worker Name:</b> _____ 0	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 15 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-14-14 <b>Received Date:</b> Jul-14-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> _____ ASB-0414-0117-AW <b>Worker ID:</b> _____ ASB-1013-0415-AW <b>Worker ID:</b> _____ <b>Worker ID:</b> _____
--	--

**Project Description:** Cleaning Rooms # 13 and 12.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-140714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-140714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-140714-ASB-JS-03	Luis N Ortiz , Cleaning Room # 13	E	7:39	8:20	1.6	65.6	100	10	12.7	0.0748	0.0412	0.0748	< 0.0330
1161-140714-ASB-JS-04	Luis N Ortiz , Cleaning Room # 13	PRCE	8:21	11:50	1.6	334.4	100	14	17.8	0.0205	0.0081	0.0205	
1161-140714-ASB-JS-05	Luis N Ortiz , Cleaning Room # 13	PRCE	13:20	15:46	1.5	219.0	100	26	33.1	0.0582	0.0123	0.0582	
1161-140714-ASB-JS-06	Felix Valentin Cleaning Room # 12	PRCE	7:44	11:54	1.6	400.0	100	17	21.7	0.0208	0.0068	0.0208	
1161-140714-ASB-JS-07	Felix Valentin, Cleaning Room # 12	PRCE	13:24	15:50	1.5	219.0	100	15	19.1	0.0336	0.0123	0.0336	0.0211

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal  
T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b> _____	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b> July 25-2014
<b>Date:</b> Jul-14-14		<b>Date:</b> _____	






# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-14-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Luis N Ortiz <b>Worker Name:</b> Felix Valentin <b>Worker Name:</b> _____ 0 <b>Worker Name:</b> _____ 0						<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 15 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-14-14 <b>Received Date:</b> Jul-14-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0414-0117-AW <b>Worker ID:</b> ASB-1013-0415-AW <b>Worker ID:</b> _____ <b>Worker ID:</b> _____							
<b>Project Description:</b> Cleaning Rooms # 13 and 12.													
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-140714-ASB-JS-08	Inside Room # 13	CE	7:40	11:51	2.0	502.0	100	16	20.4	0.0156	0.0054	0.0156	
1161-140714-ASB-JS-09	Inside Room # 13	CE	13:21	15:47	2.0	292.0	100	14	17.8	0.0235	0.0092	0.0235	
1161-140714-ASB-JS-10	Inside Room # 12	CE	7:45	11:56	2.0	502.0	100	9	11.5	0.0088	0.0054	0.0088	
1161-140714-ASB-JS-11	Inside Room # 12	CE	13:25	15:52	2.0	294.0	100	12.5	15.9	0.0209	0.0092	0.0209	
1161-140714-ASB-JS-12	Outside Room # 13 ( Decom )	OS	7:41	11:52	2.5	627.5	100	7.5	9.6	0.0059	0.0043	0.0059	
1161-140714-ASB-JS-13	Outside Room # 13 ( Decom )	OS	13:22	15:48	2.3	335.8	100	5.5	7.0	0.0080	0.0080	< 0.0080	
1161-140714-ASB-JS-14	Outside Room # 12 ( Decom )	OS	7:46	11:58	2.5	630.0	100	4.5	5.7	0.0035	0.0043	0.0043	
<i>MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.</i>													
<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627			<b>Signature:</b> _____			<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229			<b>Signature:</b>  July 25-2014				
<b>Date:</b> Jul-14-14						<b>Date:</b> _____							






# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-14-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> Jose A Santos <b>Delivery By:</b> Jose A Santos <b>Received By:</b> Jose A Santos <b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Luis N Ortiz <b>Worker Name:</b> Felix Valentin <b>Worker Name:</b> _____ 0 <b>Worker Name:</b> _____ 0						<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 15 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-14-14 <b>Received Date:</b> Jul-14-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-0414-0117-AW <b>Worker ID:</b> ASB-1013-0415-AW <b>Worker ID:</b> _____ <b>Worker ID:</b> _____							
<b>Project Description:</b> Cleaning Rooms # 13 and 12.													
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-140714-ASB-JS-15	Outside Room # 12 (Decom)	OS	13:26	15:54	2.3	340.4	100	6.5	8.3	0.0094	0.0079	0.0094	
MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.													
<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627			<b>Signature:</b> _____		<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229			<b>Signature:</b> 		<b>Date:</b> July 25 2014			





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analyzed By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>15</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>Luis N Ortiz</u> <b>Worker ID:</b> <u>ASB-0414-0117-AW</u> <b>Worker Name:</b> <u>Felix Valentin</u> <b>Worker ID:</b> <u>ASB-1013-0415-AW</u> <b>Worker Name:</b> _____ <b>Worker ID:</b> _____ <b>Worker Name:</b> _____ <b>Worker ID:</b> _____
---	--

**Project Description:** Cleaning Rooms # 13 and 12.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS14071401	Jul-14-14	1161-140714-ASB-JS-01	Field Blank I	*****	----	----	----	----	----	---	X			---
JS14071402	Jul-14-14	1161-140714-ASB-JS-02	Field Blank II	*****	----	----	----	----	----	---	X			---
JS14071403	Jul-14-14	1161-140714-ASB-JS-03	Luis N Ortiz , Cleaning Room # 13	LV-6124	7:39	8:20	1.6	1.6	1.6	65.6	X			41
JS14071404	Jul-14-14	1161-140714-ASB-JS-04	Luis N Ortiz , Cleaning Room # 13	LV-6124	8:21	11:50	1.6	1.6	1.6	334.4	X			209
JS14071405	Jul-14-14	1161-140714-ASB-JS-05	Luis N Ortiz , Cleaning Room # 13	LV-5087	13:20	15:46	1.6	1.5	1.5	219.0	X			146
JS14071406	Jul-14-14	1161-140714-ASB-JS-06	Felix Valentin Cleaning Room # 12	LV-5087	7:44	11:54	1.6	1.6	1.6	400.0	X			250
JS14071407	Jul-14-14	1161-140714-ASB-JS-07	Felix Valentin, Cleaning Room # 12	LV-5093	13:24	15:50	1.6	1.5	1.5	219.0	X			146
JS14071408	Jul-14-14	1161-140714-ASB-JS-08	Inside Room # 13	LV-5093	7:40	11:51	2.0	2.0	2.0	502.0	X			251
JS14071409	Jul-14-14	1161-140714-ASB-JS-09	Inside Room # 13	LV-2022	13:21	15:47	2.0	2.0	2.0	292.0	X			146

<b>Turn Around Time: Normal: 7 days</b> <u>  X  </u>				<b>Rush: 24 hours</b> _____		<b>Rush: 16 hours</b> _____	
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:	
Jose A Santos						Jose A Santos	
Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	
Jul-14-14						Jul-14-14	

July 25 2014





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE \_\_\_\_ OF \_\_\_\_

Customer Name: <b>Homeca Recycling and Demolitions</b>	Project Name: <b>1 ra Unidad Esc Jorge Lucas Valdiviezo</b>	
Contact: <b>Melvin Feliciano</b>	Total Samples: <b>15</b>	Job Number: <b>ENJ-1161</b>
Phone / Fax/Email: <b>787-426-1597</b>	Worker Name: <b>Luis N Ortiz</b>	Worker ID: <b>ASB-0414-0117-AW</b>
Collected By: <b>Jose A Santos</b> <b>ASB-0912-0558-MS</b>	Worker Name: <b>Felix Valentin</b>	Worker ID: <b>ASB-1013-0415-AW</b>
Analized By Lab: <b>Altol Chemical Environmental Laboratory, Inc.</b>	Worker Name: _____	Worker ID: _____
AIHA Lab ID: <b>199763</b>	Worker Name: _____	Worker ID: _____

Project Description: Cleaning Rooms # 13 and 12.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS14071410	Jul-14-14	1161-140714-ASB-JS-10	Inside Room # 12	LV-2019	7:45	11:56	2.0	2.0	2.0	502.0	X			251
JS14071411	Jul-14-14	1161-140714-ASB-JS-11	Inside Room # 12	LV-2019	13:25	15:52	2.0	2.0	2.0	294.0	X			147
JS14071412	Jul-14-14	1161-140714-ASB-JS-12	Outside Room # 13 ( Decom )	LV-5052	7:41	11:52	2.5	2.5	2.5	627.5	X			251
JS14071413	Jul-14-14	1161-140714-ASB-JS-13	Outside Room # 13 ( Decom )	LV-5052	13:22	15:48	2.5	2.3	2.3	335.8	X			146
JS14071414	Jul-14-14	1161-140714-ASB-JS-14	Outside Room # 12 ( Decom )	LV-6268	7:46	11:58	2.5	2.5	2.5	630.0	X			252
JS14071415	Jul-14-14	1161-140714-ASB-JS-15	Outside Room # 12 ( Decom )	LV-6268	13:26	15:54	2.5	2.3	2.3	340.4	X			148

Turn Around Time: Normal: 7 days <u>  X  </u>				Rush: 24 hours _____		Rush: 16 hours _____	
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:	
Jose A Santos						Jose A Santos	
Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	Date: _____ Time: _____	
Jul-14-14						Jul-14-14	

*July 25-2014*





**ALTOL ENVIRONMENTAL SERVICES, INC.**  
PO BOX 359 MERCEDITA, PR 00715-0359  
**FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS**

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-15-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> José A Santos <b>Delivery By:</b> José A Santos <b>Received By:</b> José A Santos <b>Analyzed By:</b> José A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Héctor Montañez <b>Worker Name:</b> Jorge Torres <b>Worker Name:</b> _____ 0 <b>Worker Name:</b> _____ 0	<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 15 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-15-14 <b>Received Date:</b> Jul-15-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> _____ ASB-1013-0416-AW <b>Worker ID:</b> _____ ASB-1213-0504-AW <b>Worker ID:</b> _____ <b>Worker ID:</b> _____
---	--

**Project Description:** Cleaning Rooms # 13 and 11.

Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-150714-ASB-JS-01	Field Blank I	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-150714-ASB-JS-02	Field Blank II	FB	----	----	----	---	100	0	0.0	----	----	----	
1161-150714-ASB-JS-03	Héctor Montañez, Cleaning Room # 13	E	7:28	8:10	1.6	67.2	100	5.5	7.0	0.0401	0.0402	< 0.0402	< 0.0221
1161-150714-ASB-JS-04	Héctor Montañez, Cleaning Room # 13	PRCE	8:10	11:40	1.6	336.0	100	10.5	13.4	0.0153	0.0080	0.0153	
1161-150714-ASB-JS-05	Héctor Montañez, Cleaning Room # 13	PRCE	13:18	15:50	1.5	228.0	100	17.5	22.3	0.0376	0.0118	0.0376	
1161-150714-ASB-JS-06	Jorge Torres, Cleaning Room # 11	PRCE	9:30	11:44	1.6	214.4	100	21.5	27.4	0.0492	0.0126	0.0492	
1161-150714-ASB-JS-07	Jorge Torres, Cleaning Room # 11	PRCE	13:22	15:54	1.5	228.0	100	23.5	29.9	0.0506	0.0118	0.0506	0.0297

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627	<b>Signature:</b> _____  <b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b>  Date: <u>July-25-2014</u>
<b>Date:</b> Jul-15-14		







# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions						<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo							
<b>Contact:</b> Melvin Feliciano						<b>Total Samples:</b> 15 <b>Job Number:</b> ENJ-1161							
<b>Phone / Fax/Email:</b> 787-426-1597						<b>Custody Record #:</b>							
<b>Sampling Date:</b> Jul-15-14 <b>Analytical Method:</b> NIOSH 7400						<b>Collected ID:</b> ASB-0912-0558-MS							
<b>Collected By:</b> José A Santos						<b>Delivery Date:</b> Jul-15-14							
<b>Delivery By:</b> José A Santos						<b>Received Date:</b> Jul-15-14							
<b>Received By:</b> José A Santos						<b>AIHA Lab ID:</b> 199763							
<b>Analyzed By:</b> José A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b>						<b>Worker ID:</b> ASB-1013-0416-AW							
<b>Worker Name:</b> Héctor Montañez						<b>Worker ID:</b> ASB-1213-0504-AW							
<b>Worker Name:</b> Jorge Torres						<b>Worker ID:</b>							
<b>Worker Name:</b>						<b>Worker ID:</b>							
<b>Worker Name:</b>						<b>Worker ID:</b>							
<b>Project Description:</b> Cleaning Rooms # 13 and 11.													
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-150714-ASB-JS-08	Inside Room # 13	CE	7:29	11:41	2.0	504.0	100	7.5	9.6	0.0073	0.0054	0.0073	
1161-150714-ASB-JS-09	Inside Room # 13	CE	13:19	15:51	2.0	304.0	100	11	14.0	0.0177	0.0089	0.0177	
1161-150714-ASB-JS-10	Inside Room # 11	CE	9:31	11:45	2.0	268.0	100	18	22.9	0.0329	0.0101	0.0329	
1161-150714-ASB-JS-11	Inside Room # 11	CE	13:23	15:55	2.0	304.0	100	22	28.0	0.0355	0.0089	0.0355	
1161-150714-ASB-JS-12	Outside Room # 13 ( Decom)	OS	7:30	11:42	2.5	630.0	100	3.5	4.5	0.0027	0.0043	< 0.0043	
1161-150714-ASB-JS-13	Outside Room # 13 ( Decom )	OS	13:20	15:52	2.3	349.6	100	4.5	5.7	0.0063	0.0077	< 0.0077	
1161-150714-ASB-JS-14	Outside Room # 11( Decom)	OS	9:32	11:46	2.5	335.0	100	10	12.7	0.0146	0.0081	0.0146	
<b>MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.</b>													
<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627			<b>Signature:</b>			<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229			<b>Signature:</b>   				
<b>Date:</b> Jul-15-14						<b>Date:</b>							





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions <b>Contact:</b> Melvin Feliciano <b>Phone / Fax/Email:</b> 787-426-1597 <b>Sampling Date:</b> Jul-15-14 <b>Analytical Method:</b> NIOSH 7400 <b>Collected By:</b> José A Santos <b>Delivery By:</b> José A Santos <b>Received By:</b> José A Santos <b>Analyzed By:</b> José A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b> <b>Worker Name:</b> Héctor Montañez <b>Worker Name:</b> Jorge Torres <b>Worker Name:</b> _____ 0 <b>Worker Name:</b> _____ 0						<b>Project Name:</b> 1 ra Unidad Esc Jorge Lucas Valdiviezo <b>Total Samples:</b> 15 <b>Job Number:</b> ENJ-1161 <b>Custody Record #:</b> _____ <b>Collected ID:</b> ASB-0912-0558-MS <b>Delivery Date:</b> Jul-15-14 <b>Received Date:</b> Jul-15-14 <b>AIHA Lab ID:</b> 199763 <b>Worker ID:</b> ASB-1013-0416-AW <b>Worker ID:</b> ASB-1213-0504-AW <b>Worker ID:</b> _____ <b>Worker ID:</b> _____							
<b>Project Description:</b> Cleaning Rooms # 13 and 11.													
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-150714-ASB-JS-15	Outside Room # 11 ( Decom)	OS	13:24	15:56	2.3	349.6	100	11.5	14.6	0.0161	0.0077	0.0161	
MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.													
<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787-507-1627			<b>Signature:</b> _____		<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229			<b>Signature:</b> <i>[Signature]</i> Date: <i>July-25-2014</i>					
<b>Date:</b> _____					<b>Date:</b> _____								





# ALTOL ENVIRONMENTAL SERVICES, INC.

PAGE \_\_\_\_ OF \_\_\_\_

PO BOX 359 MERCEDITA, PR 00715-0359

## CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>José A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analyzed By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>15</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>Héctor Montañez</u> <b>Worker ID:</b> <u>ASB-1013-0416-AW</u> <b>Worker Name:</b> <u>Jorge Torres</u> <b>Worker ID:</b> <u>ASB-1213-0504-AW</u> <b>Worker Name:</b> _____ <b>Worker ID:</b> _____ <b>Worker Name:</b> _____ <b>Worker ID:</b> _____
---	---

**Project Description:** Cleaning Rooms # 13 and 11.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS15071401	Jul-15-14	1161-150714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---
JS15071402	Jul-15-14	1161-150714-ASB-JS-02	Field Blank II	-----	----	----	----	----	----	---	X			---
JS15071403	Jul-15-14	1161-150714-ASB-JS-03	Héctor Montañez, Cleaning Room # 13	LV-6124	7:28	8:10	1.6	1.6	1.6	67.2	X			42
JS15071404	Jul-15-14	1161-150714-ASB-JS-04	Héctor Montañez, Cleaning Room # 13	LV-6124	8:10	11:40	1.6	1.6	1.6	336.0	X			210
JS15071405	Jul-15-14	1161-150714-ASB-JS-05	Héctor Montañez, Cleaning Room # 13	LV-5087	13:18	15:50	1.6	1.4	1.4	212.8	X			152
JS15071406	Jul-15-14	1161-150714-ASB-JS-06	Jorge Torres, Cleaning Room # 11	LV-5087	9:30	11:44	1.6	1.6	1.6	214.4	X			134
JS15071407	Jul-15-14	1161-150714-ASB-JS-07	Jorge Torres, Cleaning Room # 11	LV-5093	13:22	15:54	1.6	1.5	1.5	228.0	X			152
JS15071408	Jul-15-14	1161-150714-ASB-JS-08	Inside Room # 13	LV-5093	7:29	11:41	2.0	2.0	2.0	504.0	X			252
JS15071409	Jul-15-14	1161-150714-ASB-JS-09	Inside Room # 13	LV-2022	13:19	15:51	2.0	2.0	2.0	304.0	X			152

**Turn Around Time:** Normal: 7 days   X   Rush: 24 hours \_\_\_\_\_ Rush: 16 hours \_\_\_\_\_

Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
José A Santos						José A Santos <i>[Signature]</i>
Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:	Date: Time:
Jul-15-14						Jul-15-14





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359  
CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE \_\_\_\_ OF \_\_\_\_

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Melvin Feliciano</u> <b>Phone / Fax/Email:</b> <u>787-426-1597</u> <b>Collected By:</b> <u>José A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analized By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>1 ra Unidad Esc Jorge Lucas Valdiviezo</u> <b>Total Samples:</b> <u>15</u> <b>Job Number:</b> <u>ENJ-1161</u> <b>Worker Name:</b> <u>Héctor Montañez</u> <b>Worker ID:</b> <u>ASB-1013-0416-AW</u> <b>Worker Name:</b> <u>Jorge Torres</u> <b>Worker ID:</b> <u>ASB-1213-0504-AW</u> <b>Worker Name:</b> <b>Worker ID:</b> <b>Worker Name:</b> <b>Worker ID:</b>
---	---

**Project Description:** Cleaning Rooms # 13 and 11.

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos			Lead Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM	Air		
JS15071410	Jul-15-14	1161-150714-ASB-JS-10	Inside Room # 11	LV-2019	9:31	11:45	2.0	2.0	2.0	268.0	X				134
JS15071411	Jul-15-14	1161-150714-ASB-JS-11	Inside Room # 11	LV-2019	13:23	15:55	2.0	2.0	2.0	304.0	X				152
JS15071412	Jul-15-14	1161-150714-ASB-JS-12	Outside Room # 13 ( Decom )	LV-5052	7:30	11:42	2.5	2.5	2.5	630.0	X				252
JS15071413	Jul-15-14	1161-150714-ASB-JS-13	Outside Room # 13 ( Decom )	LV-5052	13:20	15:52	2.5	2.4	2.4	364.8	X				152
JS15071414	Jul-15-14	1161-150714-ASB-JS-14	Outside Room # 11 ( Decom )	LV-6268	9:32	11:46	2.5	2.5	2.5	335.0	X				134
JS15071415	Jul-15-14	1161-150714-ASB-JS-15	Outside Room # 11 ( Decom )	LV-6268	13:24	15:56	2.5	2.2	2.2	334.4	X				152

<b>Turn Around Time: Normal: 7 days</b> <u>  X  </u> <b>Rush: 24 hours</b> <u>      </u> <b>Rush: 16 hours</b> <u>      </u>													
Sampling Collected by:		Relinquished by:		Received by:		Relinquished by:		Received by:		Delivery to Lab by:		Received at Lab by:	
José A Santos												José A Santos	
Date:	Time:	Date:	Time:	Date:	Time:	Date:	Time:	Date:	Time:	Date:	Time:	Date:	Time:
Jul-15-14												Jul-15-14	

July 25 2014





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

## FINAL DAILY PCM AIR MONITORING REPORT FOR FIELD ANALYSIS

<b>Customer Name:</b> Homeca Recycling and Demolitions					<b>Project Name:</b> Esc Jorge Lucas Valdivieso 1 Unidad								
<b>Contact:</b> Norma Collazo					<b>Total Samples:</b> 6 <b>Job Number:</b> ENJ-1161								
<b>Phone / Fax/Email:</b> 787-373-6722					<b>Custody Record #:</b>								
<b>Sampling Date:</b> Jul-15-14 <b>Analytical Method:</b> NIOSH 7400					<b>Collected ID:</b> ASB-0912-0558-MS								
<b>Collected By:</b> Jose A Santos					<b>Delivery Date:</b> Jul-15-14								
<b>Delivery By:</b> Jose A Santos					<b>Received Date:</b> Jul-15-14								
<b>Received By:</b> Jose A Santos					<b>AIHA Lab ID:</b> 199763								
<b>Analyzed By:</b> Jose A Santos <b>Altol Chemical Environmental Laboratory, Inc.</b>					<b>Worker ID:</b> N/A								
<b>Worker Name:</b> N/A					<b>Worker ID:</b> N/A								
<b>Worker Name:</b> N/A					<b>Worker ID:</b> N/A								
<b>Worker Name:</b> N/A					<b>Worker ID:</b> N/A								

<b>Project Description:</b> Backgrounds Collected In Room # 6 .													
Sample ID	Location	Type	TIME		FLOW RATE (LPM)	SAMPLE VOLUME (Liters)	TOTAL FIELDS COUNTED	TOTAL FIBERS COUNTED	FIBER DENSITY (f/mm2)	M.F.C (f/cc)	L.O.D (f/cc)	R.F.C (f/cc)	T.W.A 8hrs (f/cc)
			START	STOP									
1161-150714-ASB-JS-01	Field Blank I	FB											
1161-150714-ASB-JS-02	Field Blank II	FB											
1161-150714-ASB-JS-03	Background Collected in room # 6 ( East)	BG	12:19	14:22	10.0	1230.0	100	43.5	55.4	0.0173	0.0022	0.0173	<
1161-150714-ASB-JS-04	Background Collected in room # 6 ( West)	BG	12:20	14:23	10.0	1230.0	100	50	63.7	0.0199	0.0022	0.0199	

MFC = Measured Fibers Concentration. LOD = Limit of Detection. RFC = Reported Fibers Concentration. T.W.A = Time Weighted Average. PR = Personal T= Type of Sample. BG = Background. EX = Exposure. OS = Outside. PP = Preparation. RM = Removal. CE = Cleaning. CL= Clearance. E = Excursion.

<b>Reported By:</b> Jose A Santos Environmental Technician jose.santos@altolenterprises.com Phone: 787 507-1627	<b>Signature:</b>	<b>Verified By:</b> Carlos Ocasio Altol Operation Manager carlos.ocasio@altolenterprises.com Phone: 787-835-4242 / 4229	<b>Signature:</b> <i>Carlos E. Ocasio</i>
<b>Date:</b> Jul-15-14		<b>Date:</b>	<i>July-25-2014</i>





# ALTOL ENVIRONMENTAL SERVICES, INC.

PO BOX 359 MERCEDITA, PR 00715-0359

CHAIN OF CUSTODY (TRANSMITTAL SHEET FOR AIR SAMPLES)

PAGE \_\_\_\_ OF \_\_\_\_

<b>Customer Name:</b> <u>Homeca Recycling and Demolitions</u> <b>Contact:</b> <u>Norma Collazo</u> <b>Phone / Fax/Email:</b> <u>787-373-6722</u> <b>Collected By:</b> <u>Jose A Santos</u> <u>ASB-0912-0558-MS</u> <b>Analized By Lab:</b> <u>Altol Chemical Environmental Laboratory, Inc.</u> <b>AIHA Lab ID:</b> <u>199763</u>	<b>Project Name:</b> <u>Esc Jorge Lucas Valdivieso 1 Unidad</u> <b>Total Samples:</b> <u>4</u> <b>Job Number:</b> <u>ENJ 1161</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u> <b>Worker Name:</b> <u>N/A</u> <b>Worker ID:</b> <u>N/A</u>
--	--

**Project Description:** Backgrounds Collected In Room # 6 .

Lab ID	Date	Sample ID	Sample Description	Pump	Time		Flow Rate			Volume (L)	Asbestos		Lea Air	Minutes
					START	STOP	Initial	Final	Avg.		PCM	TEM		
JS15071401	Jul-15-14	1161-150714-ASB-JS-01	Field Blank I	-----	----	----	----	----	----	---	X			---
JS15071402	Jul-15-14	1161-150714-ASB-JS-02	Field Blank II	-----	----		----	----	----	---	X			---
JS15071403	Jul-15-14	1161-150714-ASB-JS-03	Background Collected in room # 6 ( East)	HV-6271	12:19	14:22	10.0	10.0	10.0	1230.0	X			123
JS15071404	Jul-15-14	1161-150714-ASB-JS-04	Background Collected in room # 6 ( West)	HV-5944	12:20	14:23	10.0	10.0	10.0	1230.0	X			123

Turn Around Time: Normal: 7 days <u>  X  </u> Rush: 24 hours <u>          </u> Rush: 16 hours <u>          </u>						
Sampling Collected by:	Relinquished by:	Received by:	Relinquished by:	Received by:	Delivery to Lab by:	Received at Lab by:
Jose A Santos						Jose A Santos <i>JS</i>
Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:	Date:      Time:
Jul-15-14						<i>July 25-2014</i>